

## TABLE OF CONTENTS

1	INTE	ODUCTION TO GENESIS SPECTRUM	.1
	1.1	README.TXT FOR THIS RELEASE	.2
2	QUIC	CK START	.5
3	МАН		7
5			
	3.1	Pull Down Menus	
	3.2	THE TOOLBAR	
	3.3	THE MAIN SPECTRUM PANEL	
	3.4		
	3.5	THE SPECTRUM COLLECTION WINDOW	
	3.6	OTHER PANEL VIEWS	
4	SET	UP AND CALIBRATION	11
	4.1	MICROSCOPE PARAMETERS	11
	4.2	DETECTOR GEOMETRY PARAMETERS	12
	4.3	CALIBRATION	14
	4.3.1	When to Calibrate?	14
	4.3.2	1	
	4.3.3	Automatic Calibration	
	4.3.4	Manual Calibration	
	4.3.5	Example Calibration Log File	17
5	SPE	CTRUM BASICS	19
	5.1	SETTING THE COUNT RATE AND DEAD TIME	19
	5.2		
	5.3	SPECTRUM COLLECTION	
	5.4	SPECTRUM VIEWING	
	5.4.1	Zooming	
	5.4.2	Energy Scale	
	5.4.3	Gridlines	23
	5.4.4	Logarithmic Scale	23
	5.4.5	Color Selection	
	5.4.6	Blank Screen	
	5.4.7	1	
	5.5	Adding Labels and Text	
	5.5.1	Spectrum Label	
	5.5.2	Adding Text	
	5.6		
	5.6.1 5.6.2	How to Save How to Save In Sequence	
	5.63	Spectrum file Parameters	
	5.7	PRINTING SPECTRA	
	5.8	RECALLING STORED SPECTRA	
	5.8.1		
	5.8.2		
	5.9	PROJECT MODE	
	5.10	EDAX REPORT GENERATION	
6	PEAK	IDENTIFICATION AND QUALITATIVE ANALYSIS	35
	6.1	AUTO PEAK IDENTIFICATION	
	6.1.1		
	0.1.1		,,

	6.1.2	Z List	
	6.2	MANUAL PEAK IDENTIFICATION	
	6.2.1	Element Markers	
	6.2.2	Halographic Peak Deconvolution	
	6.2.3	Spectrum Artifacts	
	6.2.4	Overlapping Peaks	
	6.3	THE EPIC TABLE	
	6.3.1	The Omitted Elements	
	6.3.2	The Compound Calculation Utility	
	6.4	REGIONS OF INTEREST	
	6.4.1	Auto ROIs	
	6.4.2	Editing ROIs	
	6.5	THE RATEMETER	
	6.6	COMPARING SPECTRA	
	6.7	SPECTRUM PROCESSING	
	6.7.1		
	6.7.2	Subtract Spectra	
	6.7.3	Multiply by Constant	
	6.7.4	Normalize	
	6.7.5	Remove Escape Peaks	
	6.7.6	Smoothing	
	6.7.7	Generating Peaks	
	6.7.8	Subtracting Deconvolution	
_	0.114		
7	QUA	NTIFICATION	
	7.1	QUANTIFICATION SETUP	59
	7.2	BACKGROUND FITTING	59
	7.2.1	Automatic Background	60
	7.2.2	Manual Background	61
	7.2.3	Auto to Manual	61
	7.2.4	Curve or Linear Options	61
	7.2.5	Concentration Background	61
	7.2.6	Background Subtraction	
	7.3	STANDARDLESS QUANTIFICATION	63
	7.4	QUANTIFICATION RESULTS	64
	7.4.1	Saving the Results	66
	7.5	QUANTIFICATION OPTIONS	66
	7.5.1	The ZAF List	67
	7.5.2	Type Options	68
	7.6	USING STANDARDS	70
	7.6.1	Compound Standards	
	7.6.2	Pure Element Standards	72
	7.7	SEC FACTORS	
	7.8	OTHER QUANTITATIVE TECHNIQUES	74
	7.8.1	Coating Correction	74
	7.8.2	3	
	7.9	VARIABLE PRESSURE QUANTIFICATION	
	7.10	THE MATCH OPTION	78
8	AUT	O SPECTRUM PROCESSING	79
	8.1	AUTO COLLECTION SETUP	
	o. 1 8.2	AUTO COLLECTION SETUP	
	U.Z		
	-		
	8.3	PROCESSING SPECTRA FROM DISK	81
	8.3 <i>8.3.1</i>		

9.1	QUANTIFICATION: TEM MATERIALS METHODS	
9.1.1	Z List	
9.1.2	Type (Elements, Oxides, Oxy by Diff)	
9.1.3	K Factor	
9.1.4	Corrections	
9.1.5	Starting quantification	
9.1.6	Results Options	
10 TEM	BIOLOGICAL OPTION	
10.1	Quantification: TEM Biological Methods	
10.1.1		
10.1.2	Results	
10.1.3		
10.1.4	S Factors	
10.1.5	Organic Matrix	
10.1.6	5 Starting Quantification	
10.1.6 10.1.7	Starting Quantification	

# **1** INTRODUCTION TO GENESIS SPECTRUM

The GENESIS software screen-display consists of a window with Tabs such as Spectrum, Image, Maps/Line, Particles, Multi Point, GSR and WDS. The number of Tabs visible will depend upon the specific options purchased by the user. The GENESIS software first opens on the Spectrum Tab. Basic Spectrum Tab features are supplied with every GENESIS package. Additional quantification features within the Spectrum Tab will be activated as per the options purchased.

The GENESIS Spectrum User's Manual describes the features available within the Spectrum Tab of the Genesis software. The basic Spectrum package will provide the SEM Bulk Method quantification using the ZAF algorithm. Optional quantification methods may be purchased that provide for SEM Bulk Methods using PhiZAF and/or PhiRhoZ algorithms, and TEM Methods for either Materials or Biological samples. If additional options have been purchased the user can easily switch between quantification methods using a right mouse click on Quant Methods. Chapters 1 through 6 deal with the features that are common to all quantification models. Chapters 7 describes the SEM quantification models (ZAF, PhizZAF and PhiRhoZ). Chapters 9 and 10 cover the TEM Materials and TEM Biological quantifications respectively.

The basic Spectrum Tab deals with EDS spectrum collection, peak identification and quantitative analysis. Rigorous quantitative analysis with or without standards is available. In addition features for dealing with special cases such as oxides, coating and light element adjustment, and low vacuum quantification are available under the Spectrum Tab. Quantification results can be displayed or printed with several user selectable options. Additionally custom reports can be sent to Microsoft Word with just one click of a button.

In order to share the spectral data and the peak list between the various Tabs an "Import Spectrum" feature has been provided. Data is not shared between the Tabs unless it is imported from another Tab.

If a system is equipped with more than one analyzer boards it is possible to switch between analyzers from the software using a drop down box in the toolbar. However, for systems with more then one analyzer board, only one Tab can be collecting live data at any given time. Attempting to collect live data simultaneously in two Tabs will display a warning message and continue with the already active collection. While data is being collected in any one of the GENESIS Tabs, the user may wish to continue with spectrum processing in another tab.

## 1.1 Readme.txt for this release

1. System Disk requirements: minimum version 5.10

Note : This package is a pre-requisite to running any other Genesis software.

### (Software Changes : ( #xxx ) are from EDAX Software Change Database & Team2)

2. Problems fixed and features added since 3.60:

- Updated DCOM Document.
- Improved data output to the config files, to prevent corruption from occurring.
- GenTabs fix for running Genesis with Delphi Integrated.
- Fixed problem where when Genesis was minimized on Windows XP the minimized window wasn't drawn properly on the desktop.
- Calibration .csv file doesn't log properly the analyzer temperature for DPP-2 board.

- Report Generator doesn't show the quant results if Multiple,K-Ratio,ZAF check boxes are deselected.

- HT not updated properly when software starts.

3. Changes Since Version 3.60:

- Added "Extended Data Reporting" option to spectrum processing dialog. This mode is only supported in SEM Quant Modes, and is meant to provide full quant details to spectral data acquired. Note: If more then 28 elements are quantified, Microsoft Excel is limited to displaying the first 256 columns of data.

- Added Beam Current button to Spectrum Collection - Geometry area of control panel, to read the Beam Current from the microscope.

- Added DPP-2 Digital SCA support. 8 Digital SCA's are supported for the DPP. The enabling of these signals, pulse polarity and pulse width MUST be setup in the DppShell program. This is done at the bottom of the "EDS" panel.

- Added support for DPP-2FR board.
- Project mode added to File menu.

- Added launching of Spectrum Utilities via the "File Spectrum Utility..." menu.
- Added Y-Axis Intensity Scaling option on Spectrum Display & Printout.
- 4. Changes since version 4.52
- Fix reported crash when using spectrum compare mode with Project mode and long paths / filenames.
- Fix crash when clicking on File Print Setup and Cancel when Microscope control panel is displayed.
- Added Spectrum Overlay (A/B) support for EDAX Report DOC files generated.
- 5. Changes since version 4.60
  - Fixed bug with M lines not showing up in the 'Possible' lines list of the Peak ID panel when moving the spectrum cursor with the directional keys.
- 6. Problems fixed since 4.61
  - ECON Reported problem from EDAX : Germany (#286)
  - Fixed problem with SCA's not working on DPP boards via new Hex files.
- 7. Changes since version 4.61
  - Added selection to input the vertical scale value in spectra view window. (# 208).

- Added automatic selection of amplifier pulse processing time to optimize the throughput, based on input count rate. (#256).

# 2 QUICK START

- 1. Select an Amp time based on the count rate so that the dead time is between 20 and 40%.
- 2. Set a preset collection time, if desired. This will stop the spectrum collection automatically.
- 3. Start and stop spectrum collection using the "Collect" button. If a preset has been selected, start the collection using the "Collect" button and it will stop automatically.
- 4. Adjust the view of the spectrum by placing the black cursor on the area of interest by clicking with the mouse, and then use the "expand" and "contract" keys. The spectrum display can also be adjusted by clicking and dragging with the mouse.
- 5. Click the "Peak Id" button for an automatic peak identification.
- 6. The "HPD" is used for peak identification confirmation. When the HPD button is clicked, a theoretical spectrum is drawn on the collected spectrum based on the identified peaks and the collection parameters.
- 7. Type in a spectrum label with up to 216 characters. The label will be saved and printed with the spectrum.
- 8. For standardless quantification results, click the "Quantify" button. The results will use an automatic background subtraction and will be normalized to 100 percent.
- 9. The spectrum and quantification results can be printed on one page by clicking on the print button available in the results dialogue box.
- 10. The spectrum can be saved by clicking on the saved button and selecting a file name (.spc as the extension) and location.



# 3 MAIN WINDOW OVERVIEW

The Spectrum tab consists of a main control panel on the right hand side of the screen, a status bar, a toolbar across the top of the screen and a spectrum display. The main control panel contains buttons for the most frequently used functions for spectrum collection and quantification. Each section of the panel can be expanded to view advanced feature buttons.

## 3.1 Pull Down Menus

The pull down menus offer selections for advanced software features and provide access to some of the less frequently used panels.

File Edit View Proc Auto Setup Window Help

- The File pull down menu consists of selections for opening, saving and printing spectrum files.
- The Edit pull down menu contains choices for adding and editing labels and text from a spectrum file as well as viewing the spectrum file parameters.
- The View pull down menu contains selections for adjusting the spectrum display on the screen and when printed.
- Proc (process) pull down menu lists the functions for spectrum processing such as background subtraction, removing escape peaks or the peak deconvolution, normalizing two spectra or adding or subtracting spectra.
- Auto pull down menu allows for the set up of automatic spectrum processing.
- The Setup pull down menu provides access to alternate control panels such as ROI, Rate-meter and Calibration.
- The Window Pull down has multiple selections for the layout of the spectrum window.
- Help-Provides access to the help files, manuals, tool tip option and the software version number.

## 3.2 The Toolbar

The toolbar is located below the pull down menu. The toolbar contains buttons for file use, spectrum collection and viewing, switching panel views and drop down selections for setting up parameters.

😂 🗳 🖶 🏥 👙 🚯 🔣 🛇 🖂 🔺 🦉 🛝 T 🗽 V 🗛 Analyzer Det 1 💌 Preset 📃 None 💌 Amp Time 50 uS 💌 👫 🏄

The functions of the toolbar buttons are as follows: Open a file
Imports a spectrum from another Tab
Save
Save spectra by automatically numbering in sequence such as sample_0001.spc etc.
Print Print
Start Spectrum Collection
Clear
$\leftrightarrow$ $\times$ $\simeq$ $\times$ Spectrum view: expand, contract, raise or lower spectrum view.
Home position of spectrum
Overlay one spectrum on top of another
T Add text to the spectrum area
Send data to a Microsoft Word template document (see the Edax Ultra Reports User's Guide for details on this documenting feature)
Analyzer Det 1 Select the analyzer board for data collection.
Analyzer Remote If the computer (e.g. Laptop) has no EDAX hardware, "Remote" will be displayed"
Preset 100  Live  Set a preset collection time
Amp Time 25.6us Select the Hardware level Processing time (time constant)
Select the panel view for Main Spectrum panel or Microscope Panel

## 3.3 The Main Spectrum Panel

The main spectrum panel is the default panel viewed on the right hand side of the screen. The panel contains the main function buttons needed for analysis. Working from the top down the buttons are in the order that they are most frequently used. To return to the main spectrum panel (from other panel views), click on the spectrum button on the right hand

side of the toolbar . Clicking on this button while the Main Spectrum panel is already open, resets the panel view and closes up any expanded sections of the panel.



In each section of the panel the small arrow buttons can be used to expand a particular section, displaying the advanced features. Right mouse clicking on the text in a section allows for parameter set up within certain sections. The current parameters, written to the right of the buttons, will update.

## 3.4 The Status Bar

The status bar at the bottom of the screen displays important parameters and status information. The information will change dynamically while the software is open. When the system is active (i.e a spectrum is being collected) the counts per second and dead time will be displayed in red. The following parameters are displayed:

```
CPS:0 DT%: Lsec:300 Cnts:896 keV:7.070 FS:6301 AmpT:40.0 Det:SUTW+ Res:139.00
```

**CPS-** current gross count rate (fast-discriminator counts)

**DT%-** dead time % (percentage of total time the spectrometer is processing or rejecting count data)

Lsec- spectrum acquisition time expressed in live seconds

Cnts- counts in the channel under the cursor

**KeV-** location of the cursor

FS- the vertical full-scale value of the spectrum in counts

**AmpT: 40** - If Auto Amp time is used this is the actual HW AmpTime.

Det- detector type

**Res-** the detector resolution.

## 3.5 The Spectrum Collection Window

The Spectrum window displays the spectrum and the label given to the spectrum. The bottom (x) axis is the energy expressed as keV and the full scale value shown in the status bar is the vertical (y) axis in counts. The window is typically viewed with one spectrum in the collection window. Multiple spectrum windows can be opened by selecting "New" from the file pull down menu. Multiple windows can be viewed in cascade or tiled format by selecting the corresponding option in the "Window" pull down menu.

## 3.6 Other Panel Views

Panels for advanced features such as regions of interest, rate meter, calibration and microscope control (systems with column control) can be accessed through the "Setup" pull down menu. The microscope control panel can also be accessed from the toolbar (the

right most icon). To return to the main Spectrum control panel click on the **L** button.

# 4 SETUP AND CALIBRATION

Proper setup of the microscope conditions and the microanalysis parameters is essential for accurate analysis. This includes setting up the microscope parameters, detector geometry parameters and system calibration.

## 4.1 Microscope Parameters

Given below is a guideline for setup of the microscope parameters. This involves selection of the location, working distance and magnification needed for the analysis.

- 1. The microscope can be placed in the desired scan mode, either rastering over an area or in a spot mode. The spectrum that is collected is for the area that is being scanned. If the microscope is in spot mode, the x-rays are from the analysis of that spot. In the whole area mode, the x-rays are from the entire field of view.
- 2. Select an accelerating voltage that is appropriate. For x-ray analysis, a general rule is a kV of at least 2x the highest peak energy for that sample. For example, if Iron is the highest energy peak at 6.39, the minimum kV would be about 14 or 15.
- 3. Select a magnification that is appropriate for the analysis. In spot mode at high magnification, the interaction volume may be larger than the diameter of the spot. Adjust the microscope setting accordingly.
- 4. The microscope parameters, including kV, magnification and geometry are read automatically on any system that has column control. If the system does not include column control the microscope settings can be entered into the edit box at the top of the main panel (kV and tilt). The geometry can be entered into the edit boxes displayed in the expanded spectrum collect portion of the main panel. Type in the correct parameters and press the enter key after each parameter. Once all the correct geometry parameters are entered press "calculate" to obtain the correct take off angle.

1777	00.0	<b>T</b> (1)
κV	20.0	Tilt: (0,0

## 4.2 Detector Geometry Parameters

Every system has an ideal geometry based on the set up of that particular microscope and detector. It is important that the correct geometry be used, as it is crucial for accurate data processing.

To access the geometry settings, expand the spectrum collection portion of the analysis panel. For systems with column control, most of the parameters will be automatically updated. If you have purchased the "EDAX Beam Current Monitor" option you can read the microscope beam current directly from a Keithley Pico-ammeter, by clicking the "**Beam Crt**" button.

For systems without column control, all of the parameters can be entered into the edit boxes for the appropriate geometry setting. The values that were last entered before closing the software will be the default values when the program is started again.

Beam Crt	1.000
Geometry	/
Working Distance:	10.000
Intersection Dist:	34.000
Elevation Angle:	20.000
Azimuth Angle:	90.000
Scale Setting:	50.00
Calculate	

Check that working distance (distance between the pole piece and the sample) is set at its optimal value. Each microscope and detector has it's own optimal working distance which can be found in the "Detecting Unit Manual" that is sent with the system. The working distance can be read on the microscope or, if the EDAX system has column control, it will automatically be read into the geometry settings.

The other parameters in this window, intersection distance, elevation angle, azimuth angle and scale setting are not often changed and should match the settings that are in the "Detecting Unit Manual" as they are specific to each system set up. Once the settings are entered into the geometry panel the take off angle can be calculated based on these parameters and the working distance. This will be done automatically or manually by clicking on the calculate button. Detector options are accessed through the detector options box displayed when "Detector Options" is selected from the "Setup" pull down menu. This box is set for the type of detector that is included with the system. If the detector is an ECON (windowless) detector, this is where the window selection is made for opened or closed. Since the detector characteristics are not changeable, this box will rarely need to be updated.

The **Analyzer Type** listed is the model of data collection hardware in your system. At present this can be one of the following EDI-1, EDI-2, DPP-2, or DPP2-FR.

Detector Options		
— Detector Type ——	— Window Thickness ———	
Super UTVV 💌	Super UTW : 0.3000	um
C Open Closed	Parlodian: 0.0000	um
🔽 Sapphire	Aluminum: 0.0400	um
– Analyzer –	<ul> <li>Detector Characteristics —</li> </ul>	
Type: EDI 2	Metal Layer: 0.0080	um
13pc. 2012	Si Dead Layer: 0.0850	um
·		
Reset	Ok	Cancel

## 4.3 Calibration

Calibration must be done for each combination of time constant and eV per channel that you plan to use. The system stores all different sets of calibration values. The calibration panel can be accessed from the Setup Menu. The calibration panel allows for Automatic and Manual calibration. The automatic calibration is more accurate than the manual method.

Calibrat	ion
Auto Actual	Reference
Peak 1:	1.486
Peak 2:	8.040
Counts:	3000
lters:	6
Reso: 134.00 C Gain: 1182 F Gain: 0 Zero: 0 <b>Start</b>	
Manual	
F Gain: 0 Z	iero: 0
Reso: 134.00 B	LM: 10
Chang	je

A log file Calibrat.csv maintains a record of the date and time of each calibration and the calibration-parameters that were calculated. This file can be accessed through the explorer and is located in the Windows folder. Note that editing this file has no effect on the calibration as this is simply a log file.

### 4.3.1 When to Calibrate?

When to calibrate the system is dependent on numerous factors. Many labs must calibrate on a set schedule for quality control purposes. It is also possible to calibrate on an "as needed" basis. Checking the calibration can be done in a few ways.

- Manually place the cursor on a peak center and compare the actual placement with the theoretical peak position.
- > Noticing when the auto ID fails for peaks that are normally easily identified.
- > The HPD is misfit for all of the major peaks. (as shown below)

The effects of poor calibration are seen in the failure of auto peak ID to identify major elements in a spectrum. This leads to inaccurate quantification results and regions of interest that are partially covering the peak. In order to obtain accurate x-ray analysis data, the system must be in calibration. The HPD can be used as an indicator of an un-calibrated system. When the HPD is misfit on most of the major peaks it is often a signal that the system in need of calibration

#### C:\EDS\USR\Miscalibrated spectrum.spc



#### Label A: Miscalibrated spectrum

### 4.3.2 Calibration Samples

The recommended method for calibration uses the Al K and CuK lines. (Other samples may be used provided the peaks are widely separated and cover the required energy range). A calibration sample of both copper and aluminum is generally used for the calibration. A piece of copper tape or a copper grid on an aluminum stub will suffice, or a calibration sample with both copper and aluminum can be used.

Place the calibration sample in the microscope chamber and adjust the sample so that the field of view is roughly two-thirds copper (or so that the CuK and the AlK peaks are close to the same height). Set the microscope to 25 kV if available on the microscope. With the

calibration sample in the microscope, set the counts to an appropriate input for the time constant selected maintaining a dead time of 30 to 40 percent.

### 4.3.3 Automatic Calibration

Each time constant and eV/channel is calibrated individually. Click on the start button in the Calibration Panel. The calibration will run until the time constant is calibrated (the actual centroid position is less then 2eV of the reference value). The calculated peak centroid position will be displayed to the left of the target (reference) values after each iteration and when the calibration is complete.

Switch to the next time constant and adjust the count rate so that the dead time remains between 20 and 40 percent. Click on start and the next time constant will be calibrated. Repeat this procedure for all of the time constants that are going to be used.

The calibration panel has edit boxes for the number of counts and the number of iterations. The number of counts refers to the length of collection for each iteration. A sufficient number of counts should be set so that the spectrum is statistically accurate. Between 6,000 and 8,000 counts is common. The number of iterations is the maximum number of times that the calibration routine will be run per time constant.

If the calibration values do not converge by the final iteration, a dialogue box will appear stating that the values did not converge. The calibration values for the last iteration can be saved or the previous calibration values restored.

### 4.3.4 Manual Calibration

A manual calibration can also be performed by typing the fine gain and zero values into the edit boxes at the bottom of the calibration panel. Note that you must hit the "enter" key after every entry. If the last set of good calibration values are known, they can be entered into the edit boxes and the calibration can then be updated by hitting the "Change" button. These values can then be fine tuned by slowly increasing or decreasing the values until the peaks are in the appropriate locations.

Mar	nual		
F Gain:	0	Zero:	0
Reso:	134.00	BLM:	10
	Cha	nge	

The resolution can also be manually entered. The value should be from a previously calibrated value or should be selected to give the optimum peak fit and verified using the HPD function. The resolution is the FWHM (full width half maximum) value of the Mn K alpha peak. This value can be calculated from the FWHM values of the Cu and Al peaks.

The BLM (base line monitor) setting controls the low energy portion of the spectrum. This setting should only be adjusted with the assistance of a trained EDAX service engineer.

### 4.3.5 Example Calibration Log File

An example of the calibration log file saved in C: \ Windows\ Calibrat.csv.

EDAX Calibrati	on Log File															
Date	Time	TimCon	Reso	CGain	F Gain	Zero	CPS	EvCh	FS	ltera	Peak1	Peak2	LSecs	DeadTim	Detinput	EDI2Temp
25-Oct-2004	14:1	25.6	135.22		-1	-260	5956				0.9285	8.0393	17.8			34.84
25-Oct-2004	14 : 1	6.4	156.34	28081	-2	-6	28262	10	3029	1	0.9297	8.0396	5.3	32	1	34.78
25-Oct-2004	14:2	12.8	143.39	27296	3	-123	28218	10	3021	4	0.9298	8.0393	4.5	55	1	34.88
25-Oct-2004	14:3	3.2	178.75	29735	1	79	28718	10	3011	3	0.9292	8.0404	6.4	18	1	34.86
25-Oct-2004	14:4	3.2	173.33	29735	12	-104	44951	10	3022	2	1.4863	8.0412	4	28	1	34.8
25-Oct-2004	14:4	6.4	154.06	28081	4	-122	45228	10	3088	2	1.4857	8.0404	3.5	47	1	34.9
25-Oct-2004	14:5	12.8	142.65	27296	12	-205	13929	10	3000	2	1.4863	8.0397	8.7	33	1	34.92
25-Oct-2004	14:6	25.6	137.52	26934	0	-329	7608	10	3011	2	1.486	8.0408	13.8	37	1	34.86

# 5 SPECTRUM BASICS

This chapter describes the various spectrum features such as data collection, saving, printing, scale adjustment, and editing or resetting view and printing options.

## 5.1 Setting The Count Rate and Dead Time

Select a count rate that is appropriate for the sample and the desired analysis. For spectrum analysis it is often desired to use the best resolution possible. With the longer collection times in spectrum analysis, using a fast throughput is less of a priority than it is in mapping, where short dwell times require the maximization of throughput.

Use the microscope condenser lens setting (typically known as spot size) that yields the desired count rate. For spectrum collection, count rates often range from 1000 to 50,000 counts per second.

Select the Amp time that yields a dead time between 20 and 40 percent. The Amp time is selected from the drop down menu on the right hand side of the toolbar. For lower count rates longer processing times can be used. These provide the maximum resolution. As the count rate increases the faster amp times should be selected to maintain an appropriate dead time. The fast time constants provide for the maximum throughput. The dead time can be monitored in the status bar at the bottom of the screen.

## 5.2 Auto AmpTime

The last possible selection in the Amp Time drop down list is "Auto".

Amp Time	100 uS	•
	35 uS	~
	50 uS	-
	100 uS	
	Auto	*

This selection will automatically select the Amp Time that is closest to a 30% dead time for the current count rate. The selection of the Amp Time in this automatic mode will be initiated by pressing the collect spectrum button or the "Collect Maps" button. The data collection will start just after the selection of the amp time. The Amp Time selected will be shown in the status bar near the right side of the display. In order to effectively use this choice, all Amp Times should be calibrated on a regular basis. This selection is only possible in the Spectrum & the Maps/Line tabs of Genesis.

### 5.3 Spectrum Collection

All of the buttons for spectrum collection are located at the top of the main spectrum panel and also grouped together in the toolbar at the top of the screen.

Take-Off Angle:	20.0
Collect 1	Clear
EV/Chan: 10	0

To start collecting a spectrum, click on the "Collect" button in the main panel. To stop collection, click on the collection button again. (If a preset is set, it will automatically stop.) Collection can also be accomplished by clicking on the stopwatch button located in the toolbar. To clear a spectrum (without saving) click either the "clear" button in the

main panel, or the button in the toolbar that looks like a paint roller

If a fixed time of collection is desired, set a preset in the preset selection boxes on the right hand side of the toolbar. First select clock time, live time or ROI counts (counts within the enabled ROIs) and then the desired length of collection. The collection time can be selected from the pull down menu or by typing the value in the edit box. (Note: Preset ROI Counts can only be selected once the ROI's have been created.)

Preset	100	Live	-

## 5.4 Spectrum Viewing

The spectrum view can be adjusted to see the entire energy range and full-scale value or scaled to view a particular portion of interest. The spectrum display can also be customized for particular graphing options.

## 5.4.1 Zooming

The spectrum can be expanded and contracted by clicking and dragging while holding the left mouse button, inside the spectrum area. Moving the mouse to the right (with the left mouse button compressed) expands the spectrum while moving the mouse to the left slides the spectrum to the left. To compress the spectrum hold down the control key and drag the mouse to the left. To change the vertical scale, hold down the left mouse key and drag either up or down.

To zoom in on a selected peak in the spectrum, position the cursor by clicking the mouse on the energy (peak) of interest. Using the expand and contract keys shown below, adjust the spectrum until the desired portion of the spectrum is displayed in the window.

 $\leftrightarrow \times \bigtriangleup$  From left to right the keys are:

- > Expand horizontally about the cursor (by a factor of 2)
- Contract horizontally about the cursor (by a factor of 2)
- Expand vertically about the cursor (by a factor of 2)
- Contract vertically about the cursor (by a factor of 2)

To return the spectrum to the full-scale view, use the "home" button.

## 5.4.2 Energy Scale

To change the displayed X-axis range of the spectrum, select "Energy Scale" from the "View" pull down menu.

To change the energy scaling select **Manual** and then enter a start and end energy value. **Auto scale** will use the microscope kV of the currently displayed spectrum to determine where the end energy should be. In the Auto Scale mode, clicking on the start collection button will change the display scale to the Home End Energy value. In the Manual mode, clicking on the start collection button will not change the display scale. The **Home End Energy** determines the display range for the Home button in the toolbar. **Auto** will use the microscope kV to determine the end energy; **Manual** allows the user to choose from a range of values or to type in a desired value.

Energy Scale	Settings	>
<ul> <li>Display ar</li> </ul>	nd Collection	
C Auto Sca	le	
Manual	Start ke∨	/: 0.00
	End keV	/: 5.38
- Home End	Energy	
C Auto	Fixed	40.0 -

DT%:

### 5.4.3 Gridlines

Gridlines can be added to the spectrum display. In the "View" pull down menu, select "Grid". In the window select either horizontal or vertical lines or both. Enter the desired number of lines to be displayed and click "Ok". To remove the grid lines, open the dialogue box, & de-select the Horz/Vert checkboxes and click "Ok".

**Y-Scale** is used to enable the display the vertical scaling intensities on the left edge of the spectrum.

Grid Settings	1	🔊 Remo	te Gene	sis Speci	trum
				Proc <u>A</u> uto	
Grid No. of Lines	(	🛎 🛎		i 🗐 yz (	ð 🔊
🗹 Horizontal 🛛 🖉		🖉 c: \ed	ls\usr\c	hlor.spc	
Vertical 5	4	A: Chlo	rite (Nrı	п.%= 38	.86, 20
✓ Y Scale		Counts	0		
Ok Cancel		12k			
		10k			
		8k			
		6k			
		4k			
		2k			
		0.4	0 1	0.60	0.80

### 5.4.4 Logarithmic Scale

The spectrum can be plotted in a logarithmic scale. In the "View" pull down menu, select "Log...". Check on the Log scale box and the click "OK". This can be done before or after a spectrum is collected.

CPS:0

Select a Log Sca	le 🛛 🗙
Cog Scale	
Fullscale : 6633	Cnts
Ok	Cancel

### 5.4.5 Color Selection

The color of the spectrum, background, and many other features in the spectrum collection window can be changed by selecting "Set Colors" in the "View" pull down menu. Using the drop down menu, select one of the features. A color can then be selected by using either the color choices, RGB values or the palette.

Genesis Color	? ×
<u>B</u> asic colors:	
	•
Custom colors:	
Current selected color>>	Spectrum
	<u>R</u> ed: 255 <u>Green:</u> 0 Blue: 0
<u>C</u> ustom Colors	Apply OK Cancel

You must click the "Apply" button to update the Genesis Applications.

### 5.4.6 Blank Screen

The screen can be blanked (the whole screen appears dark) if any extraneous light needs to be removed from the microscope room. To blank the screen select "Blank Screen" from the "View" pull down menu. To return to the normal display click the left mouse button.

### 5.4.7 Window Options

Window display options for the spectrum screen include tile and cascade and can be found in the "Window" pull down menu. The options are:

- Cascade cascade all opened spectrum windows.
- > Tile tile all opened spectrum windows horizontally.
- Arrange icons arrange minimized icons at bottom of screen.
- ➤ ToolBar toggle tool bar on or off.

- Status Bar toggle status bar on or off.
- The list below the Window options displays names of spectra currently loaded, with a tick next to the one that is currently open.

### 5.5 Adding Labels and Text

A label can be given to each spectrum file with up to 216 characters. The label is saved with the spectrum file and will be printed as well as displayed with the spectrum. Text can be added anywhere in the spectrum collection area with up to 32 characters per box and ten boxes per spectrum.

### 5.5.1 Spectrum Label

To type the spectrum label, click in the label box and type the desired information. The label can also be added by selecting "Label" in the "Edit" pull down menu.

```
      Image: C:\EDS\USR\Stnlss.spc
      _ _ _ X

      A: Sample 123, location 1, spectrum 1, February 20th
      _ _ _ X
```

### 5.5.2 Adding Text

To add text, click the "T" button in the toolbar **T** or select "Add text" from the "Edit" pull down menu. Click in the spectrum area where the text is to be added. Type the desired text and then hit enter. The text is now tagged in that position.

	Sample A	
	Sample A	

To edit the text, select "Edit Text" in the "Edit" pull down menu. Click on the text to be edited and make the necessary changes. When finished, hit enter. To delete the text, select "Clear Text" from the "Edit" pull down menu. A warning box will confirm deleting the comments. \*\*\*All comments on the spectrum window will be cleared! \*\*\* Click "OK" to remove.

## 5.6 Saving to File

Edax spectrum files can be saved and recalled for data review or reprocessing at a later time. The default saved-file type is in \*.spc format. All of the collection parameters are saved with the file as well as the label and any text that was added to the spectrum area. Spectra can be saved in other file formats such as:

- (\*.bmp) The bitmap file type allows the user to save the file as an image. This file format cannot be used to recall the spectrum into Genesis but it can be used for sharing the file with other users or for the preparation of reports.
- (\*.tif) The picture can be opened in Word or Power Point using the Insert menu item to insert a Picture from File.
- Using the .csv file type allows for the user to open the file in Microsoft excel and see the number of counts that are in every channel of the spectrum. It can also be graphed in excel if desired. This allows not only for more in depth analysis but the sharing of spectrum files with people who do not have EDAX software.

## 5.6.1 How to Save

To save the current spectrum:

- Files can be saved by selecting "Save" or "Save As" from the File pull down menu. The "Save" will OVERWRITE the old file with the new data. "Save As" will open a dialogue box to select a file location and file name.
- Alternatively, click the save button in the main spectrum panel or the toolbar
   The toolbar button works like



the "Save" menu, while the large Save-button works like the "Save As" menu.

Files can be saved in the default directory or in a user created directory.

## 5.6.2 How to Save In Sequence

When several spectra are being collected and saved to the same folder, the Sequence Save feature can be quite handy. This automatically saves spectra into a predefined folder with a predefined name and appends a sequence number to the filename.

This feature can be activated from the File – Save In Sequence menu item, which brings up the following dialog box:

Save Spectra In Sequence	×
Save Spectra in Sequence	
Filename	
C:\EDS\USR\sampleA	
Ok	

To use the sequence save feature the checkbox must be checked. Also a folder location and filename prefix must by set by clicking on the Filename button. A new folder may be created if necessary by using the icon rightarrow from the dialog box that shows up after clicking on the Filename button.

To save files in sequence use the toolbar button **E**. For the filename selection shown above, the spectra will be saved as sampleA\_0001.spc, sampleA\_0002.spc etc.

### 5.63 Spectrum file Parameters

The spectrum file parameters are saved with the spectrum in each \*.spc file. These file parameters can be accessed from the "Edit" pull down menu by selecting "Spc File Parameters". The information saved with the spectrum will be displayed in the Spc File Parameters box.

The information in the Edit boxes can be changed by typing the correct data into the Edit boxes and then resaving the file. This may be necessary if the system does not have column control and the spectrum was saved with the wrong conditions.

Spc File Parameters	
kV 15.00	Live Time : 4.2 sec
Tilt 0.00	Preset: None
Take-off 39.43	Ew/Chan : 10
Beam Curr 1.000	Amp Time : 6.4
Resolution 149.35	Analyzer : DPP-FR
Detector Type Super UTW Window Thickness Super UTW : 0.3000 Parlodian: 0.0000 Aluminum: 0.0400	Collect Date: Um Collect Time: um Collect Time: 17:38:57
Use Current Energy List	
Ok	Cancel

## 5.7 Printing Spectra

Spectra can be printed with or without quantitative results.

To print a spectrum, click the print button in the main spectrum panel or in the toolbar.



9			20	
2	-	- 6	с.	
-	-	-	п.	

This will print the spectrum as it is currently viewed on the screen. Printing can also be accomplished by selecting "print" from the "file" pull down menu.

To change the layout of the printing, select "Print Setup" from the "file" pull down menu. This will display a window that will allow for changing the printing format including selecting a printer, changing the paper type and the paper orientation. The displayed window will be specific to the printer that is currently being used.

To change the type and amount of data that is printed, select "Page Setup" from the file pull down menu. This window will enable the print layout to be further customized by the user. Select which data to print by checking in the appropriate box. Some of the options refer to the appearance of the spectrum. The spectrum can be printed as an outline to save on ink usage in filling it up with color. It can also be printed in black and white for easier photocopying. The selections for Quantification are further described in Chapter 6.

Page Setup	
✓ Filename	✓ Date and Time
🔽 Label	Spectrum
🔽 Parameters	C Current
Spectrum	
🔽 Count Status	Outline Mode
🔽 Border	🔽 Overlay
🔽 Axis/Grid	Deconvolution
Element Markers	🔽 Background
Color C	Black and White
Multiple Results	🔽 At % 🔽 Wt %
Methods	🗹 K Ratio 🛛 🗹 ZAF
— Margins ———	
Top : 1.00 in	Left : 1.00 in
Font Courier N	ew Default
Ok	Cancel

## 5.8 Recalling Stored Spectra

Spectra saved in the \*.spc file format can be recalled into the Genesis software for spectral processing and/ or review.

Spectrum files that have been saved can be opened by using the open button on the toolbar, or by selecting "Open" in the "File" pull down menu. The desired file can be located and selected from the "Open" dialog box. Click on "Open" to open the selected file. Multiple spectrum windows can also be opened by selecting "New" in the "File" menu.

Spectra from other Genesis Tabs can be brought in by using the "Import Spc From…" item in the "File" menu. This displays a popup menu offering a selection for the Tab to import from:



Only the submenus for packages installed are activated. "Restore" will restore the original spectrum before importing back into the current view.

### 5.8.1 File or Current Parameters

When the file has been selected, a window entitled "File or Current Parameters" will be displayed. In this window, the user has the option to open the file with the current element list, regions of interest, background and analysis conditions, or with the settings that were saved with the file. A combination of both saved and current settings can be used. Select the desired parameters and then click "Ok". Use the "all current" or "all file" for easy selection if not using a combination of both.

File or Current Par	rameters 🗙	
	Parameters or File Parameters	
– Peak List ––––	– Background –	
C Current	C Current	
File	File	
Roi List	<ul> <li>Conditions</li> </ul>	
C Current	C Current	
File	File	
All Current	View All File	
	Ok 1	
	UK	
**Note**: It is not recommended to use current parameters, as they may not relate to the stored spectrum, and will cause subsequent quantifications to be inaccurate.

The "View" button in the File or Current Parameters dialog box will open another window that allows the user to view the parameters that are saved with the file including the element list, regions of interest, background and conditions. This box is extremely useful for reviewing collection information at a later date. The settings that are currently selected are also displayed in the window.

File and Current Parameters	×
Peak List	Background
File Current	File Current
Num Elements : 0 0	Method : Auto Auto Type : Curve Curve Start Energy : 0.00 0.00 End Energy : 40.00 40.00 Mum Points · 0 0
ROI List File Current	Conditions File Current
Number of ROIs: 0 0	Voltage: 15.00 0.00 Stage Tilt: 0.00 0.00 Take-off: 35.03 30.34 Beam Factor: 1.00 1.00 Live Time: 240.30 38.58 Detect Type: SUTM+ SUTM+
	Ok

The lists can be used to select between the current or file parameters when a spectrum file is opened.

#### 5.8.2 Snap Spectra Viewer

If you need to examine many spectra files quickly, there is a function in one of the EDAX utility packages to do this. Click on the main menu "File - Spectrum Utility...", a new window will be displayed. From this window click on "View - Snap Spectra into Genesis Spectrum", and a small window with a list of spectra files will be displayed.

Simply by clicking on the name of the file will update that spectrum to the "Spectrum" tab. The date and time the file was stored is displayed at the bottom of the window. To the right of this you can select a new path via the ... button.



## 5.9 Project Mode

When you want to save all the data you will collect into a single folder Project mode can be used. Clicking on the **File-Project...** menu selection will display the following window where you can set the Genesis software project mode of data storage. The selection **"Use Project Mode"** is shared across all the Genesis tabs. Once you enable this mode any data from any tab will be saved to the folder name you selected, which can be changed by the use of the **Browse...** button.

Clicking the **Browse...** button is the only way you can change the path for the current project folder. You can also create new paths via this window.

If you want to have each user of the system save their data into their own folders, by using the **"Use My Documents"** method in Project mode, the data will be saved to each users individual login (My Documents) folder.

Select Project		×
Current Project Folder	:	
C:\EDAXProjects\LEX	S Jan2005 Data	
Use Project Folder	🗆 🗆 Use	'My Documents'
Browse	Cancel	ОК

Clicking the **Browse...** button will display another dialog where you can create new folders or navigate to old ones. You can also right click on a name to use the **"Rename"** function for that active folder.

Browse For Folder	? 🛛
Select Project Output Folder	
Edax32	<u> </u>
🕀 🛅 EDAX SERVICE	
😑 🛅 EDAXProjects	
🖨 🛅 March01 Data	
🗄 🗁 Fractures	
Project1	
EDAXReports	
😟 🛅 EDS	
😟 🛅 EDS-Save	
😟 💼 🔂 GSR	~
ј : : ф 🎮 тме	
Make New Folder	OK Cancel

## 5.10 EDAX Report Generation

The following text is a small section from the EDAX Ultra Reports manual. If you wish to view the entire document, click on the EDAX Genesis folder from the windows desktop, in "\ Manuals \ Genesis Ultra Report.Pdf".

Using the *Standard template*, the Genesis Spectrum Tab can insert 2 spectra with or without Quantitative results per page.



If there is no spectrum displayed read one in from disk or collect it live from the microscope, then click on the "**Quant**" button to generate quantitative results. If there are no quant results created or don't want them you will only get the spectrum displayed in the report.

 From the "W" Drop Down Button, select the *Standard Template* and then click the "W" button. If there already is a document file open the results will be appended to the existing document. You can watch the windows taskbar and see when the report data has been completely written to the report when the document name changes from "Processing Data...", back to Document....



2) Two Text Boxes above and below the spectra are inserted automatically with a Blue background. These Text Boxes can be formatted as desired or can be deleted. The Report will save this format and use it when you click the "W" again. This can only be done on the first page of the document.

To delete these Text Boxes just click on the box and press delete key.

The Header has some user specific fields, which can be edited as desired

# **6** PEAK IDENTIFICATION AND QUALITATIVE ANALYSIS

Peak identification and qualitative analysis can be accomplished using either the Peak ID section of the main spectrum panel or the expanded Peak ID panel. For an automatic peak identification, the small Peak ID panel is sufficient. Detailed options such as manual peak identification and energy data can be accessed by expanding the Peak Id panel.

Peak Fei ID	ClearAll
HPD 📊	
	\$



## 6.1 Auto Peak Identification

Auto peak identification is often a fast and effective way to identify peaks in a spectrum. When used correctly, it can be the primary method of peak identification.

Auto ID can be performed at any time during or after spectrum collection. Once spectrum collection has begun, it is best to wait until the spectrum has collected for a reasonable

amount of time so that statistically, the peak identification will be more accurate. It is appropriate to use the auto peak identification when

- All peaks are well defined
- There are no difficult peak overlaps
- The spectrum has been collected for an adequate amount of time.

To perform an Auto Peak ID for a spectrum, click the Peak ID button in the main spectrum panel. If there are peak labels displayed from a previous spectra, they can be removed by clicking on the "Clear All" button first, or they will automatically be updated when an auto ID is performed.

The peaks will be displayed with the elements symbol above the peak. The label's position is tagged to the spectrum so that it will remain with the peak position if the spectrum is expanded or contracted. There are three display options for how the peak label is written. To select the display, expand the peak ID portion of the control panel. "Elem Only" will show the element's symbol only (Fe, for example). The Shell will add which line is shown (FeK, for example) and the "Trans" (or transition) will show whether the peak is an alpha, beta, etc. When "Alpha Lines Only" is checked, only the alpha peak of each series will be displayed. If "Alpha Lines Only" is unchecked, all of the peak locations in a series will be marked.



Three examples of display options: (A)Alpha Lines Only is unchecked, (B) Alpha Lines Only is checked, (C) Alpha LinesOnly is unchecked shell and transition selected.

#### 6.1.1 Peak to Background Ratio

Changing the Peak to Background ratio setting allows the user to decide the minimum difference between a peak and the background that the automatic peak ID will use. To change the setting, click on the "Advanced" button in the expanded Peak ID Panel. Select the desired setting from the list or switch to user selected and type in a specific value. The values for the given settings are as follows:

$$\blacktriangleright$$
 Off = 0.0

- > Low = 0.4
- $\blacktriangleright$  Medium = 0.9
- ≻ High = 1.4



Selecting a higher value for the peak to background ratio means that the Auto Peak ID will ignore smaller peaks. It also diminishes problems with the false identification of peaks that do not exist when a spectrum has poor statistics or a misfit background.

The Auto ID Sample selection allows for two choices for Auto Peak Id methods. The Semicon method is a special method for resolving low energy peak overlaps. For most cases the All Types option used.

#### 6.1.2 Z List

A Z List button is provided so that the Atomic Numbers list for quantification can be adjusted manually if needed. (See quantification details in Chapter 7).



# 6.2 Manual Peak Identification

Manual Peak identification can be accomplished in several ways using the expanded Peak ID panel. Typing in known elements may be helpful if the element list or some of the elements present are known. In the Element edit box type either the element name or the elements atomic number and press enter to display the element markers. To add the element into the list click the "Add" button. This can be repeated for each known element.



The black cursor on the spectrum window can also be used to identify peaks. Click on the peak of interest. Scroll through the Possible element list to find a probable match. The list is ordered so that the peaks that are closest in energy to the cursor position are presented first in the list. Clicking on the possible elements list will display all the energies that are associated with that element on the spectrum. Highlight the element to be added to the peak ID list and click "Add". To remove an element in the list, highlight the element in the selected element box and click "Delete".

Another method for quickly adding elements to the list is by using the Z+ and Z- buttons. If there are numerous peaks of elements close in atomic number using the Z+ and Z-buttons may be used to add the elements to the Possible elements list. Click on the lowest energy peak in the group. Click the Z+ button and the element in the edit box will go to the next possible atomic number in the periodic table. The Z- goes through the periodic table in the order of decreasing atomic numbers. At any time the user can add the currently highlighted element by pressing the "Add" button.

In many cases, using the AutoPeak ID and finalizing the list manually, is the fastest and most accurate way to identify the peaks in a spectrum. In some cases, the Auto Peak ID may be correct, but the user may want to omit a particular element in the list or, an element that was not identified may be added. Making changes in the auto ID element list is easy. First, click on the "Peak ID" button in the main panel. Expand the peak ID portion of the main panel and adjust the element list, as needed, by adding or deleting elements.

## 6.2.1 Element Markers

When an element is typed into the element edit box or highlighted in the possible list or the saved element list, multicolored markers will be displayed on the spectrum area illustrating the locations and relative intensities of each peak in the series for that element. Green markers designate the K series, cyan, the L series and yellow for the M series. The element markers can be used for confirming peak identification as well as peaks belonging to different series of the same element. To view the lines for multiple elements simultaneously, hold the ctrl key and highlight the desired elements in the saved element list. To remove multiple lines click on a single element in the saved list without the ctrl key. Right mouse click clears all element markers from the display.



## 6.2.2 Halographic Peak Deconvolution

For all spectra, it is advantageous to use the EDAX HPD feature. The HPD (Halographic peak deconvolution) uses the spectrum collection parameters and the element list to draw a theoretical spectrum to compare with the collected spectrum. The HPD appears as a cyan outline drawn over the spectrum on the collected spectrum. If the HPD is misfit for a particular element, that peak can be reexamined. If all or most of the peaks are shifted in the spectrum, it is an indication that the system should be calibrated.

The HPD can be subtracted from the spectrum to show any unidentified peaks. To do this, select "Subtract Deconvolution" from the Proc (process) pull down menu. The "Undo" selection in the "Edit" pull down menu will return the spectrum to its original state.



Example A displays the correct fit for a peak containing both Silicon and Strontium.

Example B displays the misfit when a Silicon peak is incorrectly identified as Tungsten.

## 6.2.3 Spectrum Artifacts

Two anomalies that are occasionally seen in spectra are sum peaks and escape peaks. A sum peak is the processing of two x-ray events as one. Summing is more common at high count rates and fast processing times where the spectrum is dominated by a single peak. Such a sum peak will appear at two times the energy of the peak. For example, Silicon with an energy of 1.74 would have a sum peak at 3.48. To display a sum-peak marker, check the "Sum" selection box in the expanded Peak ID panel.

Marker		
🔽 Abs	🔽 Esc	🔽 Sum

When a spectrum is dominated by two nearly equal peaks it is possible to create a sum peak that is the energy of Peak A and peak B.

An escape peak is generated when the x-ray entering the detector strikes the crystal and fluoresces a Si x-ray that then leaves the detector before electrons are created from that portion of the original x-ray energy. The x-ray energy is then the energy of the characteristic x-ray minus the energy of Silicon. Escape peaks are always a small percentage of the parent peak. These peaks positions can be located by selecting the "Esc" markers in the expanded peak identification panel. The escape peak can also be removed from the spectrum by selecting "escape" in the "Proc" pull down menu. There is also a marker that can be used to mark the location of absorption edges.

## 6.2.4 Overlapping Peaks

Overlapping peaks such as Sulfur and Molybdenum can be difficult to identify. The primary method for determining if either one or both peaks are present is by using the element markers for location of overlapping peaks and the HPD. Highlighting one of the elements in the possible element list will display the element markers in the spectrum area. Note the position of the markers on the peak that is selected as well as the other peaks for that element. Select the element for which the markers look the best. Click on the HPD button and check the fit with the peak. If necessary, try the other element, and try both elements. Select the element or combination of elements that works the best.

# 6.3 The EPIC Table

The layout of the EPIC table (<u>EDAX Peak Identification Chart</u>) is based on the periodic table and contains the positions and energies of the peaks for all series of an element. The energy data in this table could be edited if needed to fine tune the Peak Identification for a specific detector.

The EPIC table can be accessed from the expanded Peak ID section by clicking on the EPIC button.



The periodic table of the elements is displayed as shown below. Clicking on any element will display the major peak positions for K, L and M alpha lines for that element in the center portion of the table.

🔛 Dx	🖬 DxEnrg32 - EDS Set 2																
Energy	<u>E</u> nergy <u>P</u> rint <u>R</u> eset <u>C</u> omp <u>O</u> xide <u>A</u> utoID <u>H</u> elp																
		Г	Fe -	26	1	ron -					7						
Wt:         55.85         Eng:         6.398         EDS Energy Table           H         Oxd:         1.5         Abs:         7.107								He									
Li	Be		Lin					L (		-		В	С	N	0	F	Ne
Na	Mg				_		_					AI	Si	Р	S	CI	Ar
K	Ca	Sc	Ti	۷	Cr	Mn	Fe	Co	Ni	Cu	Zn	Ga	Ge	As	Se	Br	Kr
Rb	Sr	Y	Zr	Nb	Mo	Tc	Ru	Rh	Pd	Ag	Cd	In	Sn	Sb	Te	L	Xe
Cs	Ba	La	Hf	Ta	¥	Re	Ôs	lr –	Pt	Au	Hg	TI	Pb	Bi	Po	At	Rn
Fr Ra Ac Ce Pr Nd Pm Sm Eu Gd Tb Dy Ho Er Tm Yb L									Lu								
ו 🖸	otal	Ka		Th	Pa	U	Np	Pu	Am	Cm	Bk	Cf	Es	Fm	Md	No	Lw

To examine the complete energy table for an element click on the element in the periodic table and then click the "EDS Energy Table" button to display the energy and relative intensities of all of the lines. The energies can be edited in this table so that the EPIC table can be customized for each detector, if desired. To edit the values, highlight the old value, type in the new value and then hit "change". If the original values need to be restored, click on the "Reset" in the EPIC table menu.

kev:		Z	2- Z+	Chang	e Ca	ncel	<u>o</u> k
Fe-26	Kev	Inten	Line	Kev	Inten	Line	Edge
Ka1	6.402	100.0	Lb4	0.792	0.5	Kab	7.107
Ka2	6.390	50.0	Lg1	0.000	0.0	L1ab	0.846
КЬ1	7.054	20.4	Lg23	0.000	0.0	L2ab	0.721
КЬ2	0.000	0.0	Ln	0.628	15.0	L3ab	0.707
КЬЗ	0.000	0.0	LI	0.615	38.0	M1ab	0.092
La1	0.705	100.0	Ma	0.000	0.0	M2ab	0.000
La2	0.705	10.0	МЬ	0.000	0.0	MЗаb	0.000
Lb1	0.718	15.0	Mg	0.000	0.0	M4ab	0.000
Lb2	0.000	0.0	Mz1	0.000	0.0	M5ab	0.000
Lb3	0.792	0.5	M2n4	0.000	0.0		

#### 6.3.1 The Omitted Elements

The Omitted element list contains 15 default elements that will not be included in an Auto Peak ID. However, they can be manually added to a peak list in the same manner as any other element. Elements can also be added or removed from the "Omitted List" if desired. To access the omitted element list, click on "AutoID" in the menu of the EPIC table. The current list of omitted elements will be shown. To add an element, simply click on that element on the EPIC chart. To delete an element, highlight the element in the list and then click "Delete". Once all of the changes have been made, click on the save button. Select the program that the list is to be applied to (**choice 9, for the Genesis Spectrum tab**) and then click "OK". To review an omitted element list, click on "read" at the bottom of the element list and then select the program for which the list is to be reviewed.

Auto ID	
Omitted E	Elem List
Total	: 15
10- Ne 18- Ar 21- Sc 36- Kr 52- Te 54- Xe 75- Re 77- Ir 84- Po 85- At 86- Rn Applica	× tion: 9
Genesis SEM	l Quant
(Bead)	<u>D</u> elete
Save	<u> </u>

#### 6.3.2 The Compound Calculation Utility

Another feature of the EPIC table is the calculation of the atomic and weight percents from a chemical formula. In the menu, click on the "Comp" selection. In the displayed window enter the elements by typing the symbol into the top edit box or clicking on the element in the main EPIC window. Enter the number of atoms in the formula unit into the At. No edit boxes and click Wt% or At% in the menu.

ľ	Calculate Compound & Others									
	<u>W</u> t% <u>A</u> t% <u>C</u> opy <u>Print</u> Othe <u>r</u> s <u>S</u> ave <u>O</u> K									
ĺ	At. N	lo:	<u> </u>	B						
		Elem	At. No	₩t%	At%					
	1	Si	1	46.745	33.333					
	2	0	2.000	53.255	66.667					
	3									
	4									
	5									
	6									
	7									

# 6.4 Regions of Interest

Regions of Interest are "windows" created on a spectrum that cover most of the energy range where x-ray counts are detected for a particular line. Regions of interest can be created manually or automatically for peaks in the ID list. The region of interest panel can be accessed through the "Setup" pull down menu by selecting "ROI/Ratemeter".

Regions o	f Interest
Name	: 0 K
Start ke∨	: 0.470
End keV	: 0.540
Enable SCA	: 🔽
SCA	: 3
Create	Auto Rois
Add	ROIs
Delete	OK 1+
Delete All	MgK 2+ AlK 3+
Delete All	SiK 4+
Change	CrK 5+
	FeK 6+
Enable	NiK 7+

The "Enable" button assigns a particular ROI to an SCA channel so that it can be used with the ratemeter or dot mapping features. ROI's that are assigned to an SCA will be drawn in color on the spectrum and will be listed with a + in the ROI list. The yellow represents SCA1, cyan is SCA 2, purple is SCA 3 and green is SCA 4. All SCAs greater than 4 will be displayed in gray. **DPP style boards only support the 16 Digital SCA outputs. The older EDI 1 and 2 boards had also a single analog SCA output.** 

## 6.4.1 Auto ROIs

Regions of interest can be created automatically by clicking on the "Auto Rois" button in the expanded Peak ID panel. This will create a "window" for each element in the peak identification list. The start and end kev values for each of the elements can be viewed in the edit boxes at the top of the screen by highlighting the element of interest in the ROI list.

## 6.4.2 Editing ROIs

To widen or narrow the window, highlight the element of interest in the ROI list and type the new start and/ or end value in the edit boxes. Click on the "Change" button.

To create a new ROI, click on the "Create" button, type in a new three letter name (bkg, for a background ROI for example) and then type in the start and end values. A new ROI can also be created by drawing a region on the spectrum using the mouse. When the create button is clicked, the mouse cursor will switch to an arrow. With the left mouse button pressed, drag the mouse over the spectrum and the start and end values will update. Once the new name and location has been selected, click on the "Add" button to insert the new ROI into the list.

To delete an ROI, highlight the ROI in the list and then click the "Delete" button. To delete the entire list, click on the "Delete All" button.

## 6.5 The Ratemeter

The Ratemeter can be accessed by clicking on the Ratemeter button below the ROI section. This will expand into a "Ratemeter" section. The Ratemeter button toggles the Ratemeter display on or off. Note that the Digital Output ratemeter functions are not available with the DPP hardware (**right hand window**), just the older EDI1+2 with IO Board hardware systems.

Ratemeter	Ratemeter
Full Scale: 29 Auto	
Setup Start	Setup
ROI CPS INT	ROI CPS INT
зік 29 2923 🔼	OK 315 75777
ClK 61 6132	MgK 259 62240
кк 71 7192	A1K 118 28497
Cor 18 1881 🔟	SiK 159 38344
Integ. Time 0.01	CrK 6 1677
	FeK 8 2155
Threshold 0	NiK 2 515
Smoothing Off	
Test Signals	
Pattern Ramp	

The ratemeter can be used to view the total number of counts in a given ROI and the calculated counts per second for that element during collection. The information will be displayed in the ratemeter portion of the ROI panel.

The ratemeter can be used to create a trace on the microscope screen of the X-position of the microscope beam. The higher the trace on the screen, the higher the relative count rate at that point.

To display the ratemeter trace:

- 1. Set up one or more ROIs in the ROI panel.
- 2. Click on the Ratemeter button at the bottom of the panel.
- 3. Highlight an ROI from the list and click on the **Start** button. (The text on the **Start** button will change to **Stop**. The spectrum display will continue to update.)
- 4. If the microscope has the ratemeter feature available, an integration time (Integ. Time) should be selected that is divisible into the line time of the

microscope. If the line time is 100 times greater than the Integration time there will be 100 measurements made during the line scanned.

To setup the Ratemeter display click on the "**Setup**" button in the Ratemeter panel. Choose the values to be displayed in the ROI list box for each ROI. Note: **Total Integrated Counts** is abbreviated to **INT** on the display. To display a ratioed value for each ROI, an ROI to which all others will be ratioed must be selected.

🖬 Setup Ratemeter Data Display	×
<ul> <li>Choose Data Display</li> </ul>	1
<ul> <li>CPS and Total Integral Counts</li> </ul>	
CPS and ROI Ratio	
O Total Integral Counts and ROI Ratio	
Ratio ROI Enabled ROI for Ratios :	1
Ok	

Two test modes are used to setup the microscope for proper deflection in the Y-axis of the profile data: Ramp & Pattern.

**Ramp**: Outputs a 10 step digital ramp from the ratemeter output to the microscope. The voltage span is from the minimum to the maximum of the Ratemeters hardware voltage range. This voltage should be applied to the microscope Line profile input. The time per step is defined by the integration time.

**Pattern**: Outputs a square wave pattern to the microscope. The voltage span is from 10% to 90% of the maximum voltage possible. The time per step is defined by the integration time.

**AUTO Button** (Next to Full Scale): This button is for the AutoScale feature. In normal operation the Fixed scale mode is used, but to setup the ratemeter on a specimen, auto scale is very useful. Auto scale should be used with integration times of 0.10 seconds or greater to improve counting statistics. To autoscale, click on the Auto button and allow time for one line scan to complete. Hitting the stop button will display the maximum counts for the selected ROI in the Full Scale edit box. This value can then be used in the Fixed Scale mode.

**Integration Time :** Defines the EDX collection time interval per ratemeter step. Typically values for actual collection should be between 0.10 and 0.30 seconds.

**Analog Smoothing :** Sets the smoothing percentage from 0% to 100% for the ratemeter analog output.

**Threshold :** A setting which inhibits the output of the ratemeter until the countrate exceeds this percentage. This is used to remove a background count from a sample and show only counts from the more intense regions of the specimen.

# 6.6 Comparing Spectra

Spectra can be overlaid on the screen (or printouts) for comparison purposes. The Single Overlay mode can compare two spectra at a time and is useful when the Swap feature is needed or when the ViP Quant feature (optional feature) is being used. The Multiple Overlay mode can compare six spectra at a time. The spectrum drawn in red is always the top level spectrum which will be used for quantification.

Open a spectrum into memory A using the "Open" selection in the "File" pull down menu. This spectrum will be displayed as the solid spectrum.

From the "View" pull down menu, select "Compare". The dialog box shown below will appear:

🗖 Compare Spectra 🛛 🛛 🔀
<ul> <li>Single Overlay</li> <li>Multiple Overlays</li> <li>Spectrum A</li> <li>Filename : genspc.spc</li> <li>Label : Stnlss Steel</li> </ul>
Vertical Scaling     Auto    Fixed     6633
Spectrum B Filename Open Label :
Vertical Scaling     Auto O Fixed
Swap A,B Ok

The display of single or the multiple overlay can be toggled on or off by clicking on the button in the toolbar.

When the Single Overlay checkbox is checked, the Open button and the Swap button are enabled. Using the "Open" button in the window, browse for and open the desired file. Click "OK" to close the window. This is the memory B Spectrum and is displayed as a black outline.

= 0	ompare Spe	ctra		X
-	Single Overlav Spectrum A Filename : genspc.s Label : Stnlss Steel		overlays	
	<ul> <li>Vertical Scaling</li> <li>Auto</li> <li>Fixed</li> </ul>	6633		
	– Spectrum B –––– Filename Label :		Open	
	- Vertical Scaling - ○ Auto			
[	Swap A,B		Ok	



By default the spectra will be scaled so that the highest peak of each spectrum will be full scale. There are four scaling options when comparing two spectra:

- ➢ Auto A and Auto B
- ➢ Auto A and Fixed B
- ➢ Fixed A and Auto B
- ➢ Fixed A and Fixed B.

To select one of these options: Click on the appropriate options in the Spectrum A and Spectrum B fields.

Fixed scaling- To specify the scale height of a spectrum, click on Fixed and highlight the field next to the Fixed label. Type in the number of counts that will represent full scale. Click on **OK** or press **Enter**. The spectrum then scales to the specified value.

To compare more than two spectra click on the Multiple Overlay checkbox:

= Compare Spectra 🛛 🛛 🔀
<ul> <li>Single Overlay</li> <li>Spectrum A</li> <li>Filename : genspc.spc</li> <li>Label : Stnlss Steel</li> </ul>
Vertical Scaling     Outline     Auto
Multi O∨erlay Filenames:Open
Ok

Use the Open button to select the files for overlay using the dialog box for file selection shown below:

Select Files	
c:\eds\USR	
Chlor.spc Copy of Chlor.spc first.spc Quiz.spc second.spc seq_0001.spc seq_0002.spc seq_0003.spc seq_0004.spc seq_0005.spc seq_0006.spc seq_0008.spc	Add
Files for Overlay: (Max 5) c:\eds\usr\Quiz.spc c:\eds\usr\Chlor.spc	Remove Clear All Ok

The path of the currently selected folder is shown in bold at the top of the dialog box. The selected files will be shown in the lower list box. Files may be selected from different folders. A maximum of five selections are permitted. Click Ok.

The 6 color display is obtained as shown below. The filenames are displayed at the top in the same color as the spectrum. The default display shows all spectra in outline mode. The top level (red) spectrum may be displayed in solid color by unchecking the Outline checkbox.

The display will show the combined peak list for all 6 spectra. However, the peak list in the Peak Id panel will be the one for the top-level spectrum (red) as this list is used for quantification.



By default all spectra will be drawn in Auto Scale mode (that is, the highest peak of each spectrum will be full scale). The scaling can be changed by clicking the Fixed radio button in the Compare Spectra dialog box. This will display the scale edit boxes which can be edited as desired.

Compare Spectra	
<ul> <li>Single Overlay</li> <li>Multiple</li> <li>Spectrum A</li> <li>Filename : 0_0P3.SPC</li> <li>Label : rr ) (Vacuum: 0.20mBar )</li> </ul>	
O Auto  ● Fixed 4737	Outline
Multi Overlay Filenames: Open c:\eds\usr\SiO2.spc c:\eds\usr\Sioxyn.spc c:\eds\usr\Stnlss.spc c:\eds\usr\seq_0007.spc c:\eds\eds\usr\location.spc	Scale 3850 4767 6633 3153 6129
	Ok

The spectra in either the Single Overlay mode or the Multiple Overlay mode can be scaled in a particular region of the spectra. To do this, select "Normalize" from the "Proc" pull down menu. Enter the keV range that the spectra are to be normalized to. Click "Ok". The two spectra will now be normalized for the counts within that keV region.

🔲 Normalize	;	×
Energy F	Range	
Start:	2.30	ke∨
End:	2.40	ke∨
Ok		Cancel

The overlaid spectra can also be printed using the File Print menu. Be sure that overlay is selected in the "Page Set Up" dialogue box that can be accessed from the "File" pull down menu.

# 6.7 Spectrum Processing

Various spectrum processing techniques are available using the spectra in memories A and B. They can be accessed from the "Proc" pull down menu. The spectrum can be restored to its original condition (as before processing) by selecting "Undo" in the "Edit" pull down menu.

#### 6.7.1 Add Spectra

The A +B function allows two spectra to be added together. Open the two spectra into memory A and memory B using the "Compare" dialogue box (selected from the "View" pull down menu). Click on A+B in the "proc" pull down menu. To undo the add function, select "Undo" in the edit pull down menu. To save the new spectrum click the save button, or select "Save As" from the file pull down menu to give the file a new name.

#### 6.7.2 Subtract Spectra

The A-B function allows for one spectrum to be subtracted from another. Open the spectrum that is to be subtracted into the "B" memory. The spectrum that is to be subtracted from should be opened into the "A" memory. Select "A-B" from the "Proc" pull down menu. To undo the subtract function, select "Undo" in the edit pull down menu. To save the subtracted spectrum hit the Save button, or select "Save As" from the file pull down menu to give the file a new name.

## 6.7.3 Multiply by Constant

The multiply function allows for the counts in a spectrum to be multiplied by two constants a and b. Select "Multiply" in the "Proc" pull down menu. Enter a constant for both A and B. In this process, a x A + b x B  $\Rightarrow$  A

Note: Only b can be a negative number.

Multiply Spectrum	×				
Enter Constants to Multipy Spectra By (A = aA + bB)					
a: <mark>1.00</mark>					
b:					
Ok Cancel					

#### 6.7.4 Normalize

The normalization process normalizes both spectra to match the counts of the specified region. Normalize allows the user to select the x-ray energy region to which two spectra are normalized. To do this, select "Normalize" from the "Proc" pull down menu. This function will not be available if there are no spectra currently in each memory. Enter the keV range that the spectra are to be normalized to. Click "Ok". The two spectra will now be normalized for the counts within that keV region.

🔲 Normalize	×
Energy Range	
Start: 2.30	ke∨
End: 2.40	ke∨
Ok	Cancel

#### 6.7.5 Remove Escape Peaks

Escape peaks can be removed from the spectrum by selecting "Escape" from the Proc pull down. The escape peaks will be removed from the spectrum and displayed as the "B" memory spectrum.

*Note: Be sure that the "B" memory spectrum does not currently contain an unsaved file in memory before subtracting the escape peaks!* 

#### 6.7.6 Smoothing

The Smooth function smoothes the displayed spectrum with a 9-point Savitsky-Golay smooth. This function can be carried out up to three times per spectrum. The Edit Undo menu item clears all the smoothes and restores the original spectrum.

## 6.7.7 Generating Peaks

Peak Generate allows the user to create a peak for a particular element with a given number of counts. In the "Proc" pull down menu select "Peak Gen". From the displayed window enter the element symbol and the number of counts to be given to the peak. The peak will display as an overlay (black outline) over the spectrum in memory A. To add the peak to the spectrum use the A+B function. It is also possible to remove a peak of this height by using the A-B function.

Peak Generation						
Element: MnK						
Height: 1000 Cnts						
Ok Cancel						

#### 6.7.8 Subtracting Deconvolution

Subtract Deconvolution allows the user to subtract the HPD from the spectrum so that any portion of the spectrum that is not fit in the HPD will remain. If an element is left out of an overlap situation the deconvolution can be subtracted so that the "hidden" peak can be identified. Set the HPD by clicking on the HPD button in the main Spectrum panel. From the "Proc" pull down menu select "Subtract Deconvolution". To return to the original spectrum select "Undo" from the "Edit" pull down menu.

# 7 QUANTIFICATION

Quantification with the EDAX system is divided into two main methods, quantitative analysis for the SEM and Quantitative analysis for the TEM. These two methods are further divided into different methods that are used for different sample types.

- For the SEM, three matrix corrections are available; ZAF, PhiZAF and PhiRhoZ.
- > In the TEM, Materials and Biological routines are available.

Depending on the set up and the options that are purchased with the system, some of, or all of these options may be available. For the TEM quantification, refer to Chapter 9 for Materials and Chapter 10 for Biological option. The following instructions refer to bulk analysis in the scanning electron microscope.

# 7.1 Quantification Setup

Any sample that is used for quantification, should be flat, polished and smooth. The geometry should be optimized and all of the parameters entered manually if the system does not include column control. Select a magnification and location that is appropriate for the sample. Remember that the quantification routine is designed based on the three assumptions of microanalysis:

- 1. The sample is smooth and polished.
- 2. The sample is homogeneous.
- 3. The sample is infinitely thick to the electron beam.

Quantification of samples that do not follow these three assumptions, a sample with inclusions for example, adds complexity and possible error to the analysis. The sample can be quantified using standards, standardless, or using any of the quantification options available in the EDAX software based on the sample characteristics.

On systems with column control, all or many of the parameters will be read automatically from the microscope. On systems without column control the parameters must be entered manually. To enter the analysis parameters and the geometry use the edit boxes at the top of the main spectrum panel (See Chapter 3). Type in the correct parameters and press the enter key after each parameter. Once all the correct geometry parameters are entered press "Calculate" to obtain the correct take off angle.

# 7.2 Background Fitting

In a spectrum there are two main types of x-rays, characteristic and background. Characteristic x-rays result from the beam's interaction with the elements in the sample, while background X-rays result from the inelastic scattering of electrons within the specimen. In quantitative analysis, the background x-rays must be subtracted from the spectrum. A blue line is drawn on the spectrum separating the characteristic x-rays from the background. The Background that is fit with a standardless quantification is an automatic, smooth fit background, by default. A manually drawn background, enhanced manual background or concentration background can be set in the expanded background panel. Once the background type is selected, the text next to the Background button will update to show the selected background type. The selected background is drawn every time the quantification button is hit or can also be set by clicking on the background button in the main control panel. The background portion of the main panel and the expanded background panel are shown below.





#### 7.2.1 Automatic Background

To set the auto background, click on the "Bkg" button. This will draw the background on the spectrum. (Performing an HPD or quantitative analysis will also automatically draw the background.) In the expanded background panel, all of the points that were picked for the background can be seen in the list box.

It is often beneficial to use the automatic background and then be able to fine tune it by making some simple adjustments using the manual method. (see the section on Auto to Manual)

## 7.2.2 Manual Background

To set a manual background, simply start at the low end of the spectrum and click on the spectrum where a background point should be. The location will be read into the edit box, then hit add. Each manual point that is shown in the list box can be manipulated using the + and - keys. Once all of the points are in place the spectrum can be quantified and/ or the background can be subtracted.

## 7.2.3 Auto to Manual

A combination of Auto and Manual methods may be used to get the best results. After doing an Auto background, expand the background portion of the main panel. Select the manual setting and then click on the >> button between the auto and manual selections. This will keep all of the points set in the automatic background, but enable the user to add, delete, raise or lower the points.

- To add a point, position the cursor on the spectrum where the point is to be added and then click "Add". Alternatively, a point can be added by typing in the keV location into the edit box.
- > To delete a point, highlight the point in the points listbox and then hit delete.
- To raise or lower a given point, highlight the point in the list and then use the + and buttons to change the point accordingly. The original position of the point is considered to be 100% so to return to the starting position either use the + and buttons or type 100 in the edit box.

## 7.2.4 Curve or Linear Options

Curve or linear background can be selected by right mouse clicking on the "Type" option next to the Bkg button. The curve background is the generally recommended type for EDS systems.

## 7.2.5 Concentration Background

Concentration background accounts for the absorption edges in the sample and in the detector. This background method can be selected by checking the concentration background check box in the expanded background panel. To perform the concentration background calculations, two points along the spectrum are needed. These two points can be chosen automatically by the software by simply selecting concentration, leaving the setting checked on auto and then clicking on the background button to set. To manually select the two points used to set the concentration background, type the selected points into the Kev1 and Kev2 edit boxes and press enter.



#### 7.2.6 Background Subtraction

The background can be subtracted by clicking on the "Subtract" button in the expanded background panel. This will remove the background from the spectrum that is currently displayed. Once the background has been subtracted, the "Undo" button directly below the subtract button will become enabled. To return the spectrum to full view, with the background, click on the undo button. The undo button works only for the last action. Shown below is a spectrum with the background subtracted.



The background will automatically be displayed after a quantitative analysis or any time that the background button is hit. By default it will be drawn as a dark blue line. This color can be changed using the View- Set Colors menu. To remove the background from the screen, right-mouse-click in the spectrum collection area. This will remove the background, HPD and element markers. The background can also be printed on the spectrum. To print the background, the "Background" check box must be checked in the Page Setup box and the background should be visible on the screen.

Once the background has been adjusted it can be saved using the .spc file format. In the "File" pull down menu, select "Save bkgd as .spc". Select a file name and then click save. The background alone will then be saved as a spectrum. Note that the background method and background points are also saved in each spc file.

## 7.3 Standardless Quantification

The standardless quantification results provide a fast quantification with an automatic background subtraction, matrix correction, and normalization to 100% for all of the elements in the peak identification list.



In many cases, a standardless quantification is desired. The standardless quantification routine can be performed by hitting the "Quant" button in the main panel. This will display a floating dialogue box with the quantification results. The Quantification Results box has buttons to print the just the results or the spectrum and results. There is also a button to access the Page Setup dialogue box to select the information that will be displayed in the printout. The information in this box can also be copied to the clipboard by highlighting the text with the mouse and then using a right mouse click and selecting "Copy". The information can then be pasted into a report.

🔲 Quantifica	tion Result	\$					×		
	C:\EDS\misc. apps\416hi.spc Label :Stainless Steel 416, 800x, whole area								
Acquisi	Acquisition Time : 14:37:17 Date : 9-Sep-1999								
Element	EDAX ZAF Quantification (Standardless) Element Normalized SEC Table : Default								
Elem	Elem Wt % At % K-Ratio Z A F								
AlK SiK MoL S K									
Page Setup Print Results Print Spc and Results Ok									

## 7.4 Quantification Results

The user has various options available for selecting the information to be displayed in the quantification results box. Some options are:

- K-Ratios- The ratio of the intensity of an element in the sample to the intensity of the pure element under same conditions.
- ZAF- The atomic number, absorption and fluorescence corrections.
- Net Intensities- Intensity of a peak minus the background after deconvolution.
- Background Intensity- Intensity considered to be background
- (Bremsstrahlung) that is subtracted when determining the net intensity.
- Intensity Error- Relative statistical error for the elemental peak intensity. Expressed as 1 standard deviation.
- Peak to Background Ratio (p/b)- The ratio of counts in a peak to the counts in the subtracted background

The data to be displayed can be selected in two places, the Page Setup dialogue box and in the "Results" selections in the expanded quantification panel. Click on the Results button in the expanded Quant panel. This will display the section for selecting the intensities and/or percent concentrations. The page set up button that is now available can be used to access the Page Setup dialogue box. The Page Setup box can also be accessed from the File pull down menu.



In the Page Setup box, the quantification section allows for the selection or de-selection of the Atomic percentages, weight percentages, K-ratios, ZAF correction values, methods, and multiple results.

🛛 Quantification 🛛 —		
Multiple Results	🔽 At %	🔽 Wt %
Methods	🔽 K Ratio	🔽 ZAF

To save the quantitative results click on the "Save" button in the expanded Quant panel. From the displayed window select the file location, designate a file name and select the file type as .csv. The quant results can then be opened into Microsoft Excel. This is most beneficial when the results are to be reviewed, sorted or plotted in Excel. Summary statistics are more easily obtained if the "Multiple results" option is selected.

The Multiple results checkbox is used to display the quantification results for multiple spectra in the same dialogue box. There are two different ways that the results can be shown by selecting multiple results in either the Page Setup box or in the expanded Quant portion of the main panel.

- In the page set up dialogue box, checking multiple results will create a table that has a separate row for each analysis. (See example below)
- Using the multiple results selection in the expanded quantification panel will create a table that allows the data to be displayed in sequence for multiple spectra or multiple analyses.
- By selecting both multiple results choices a table will results that is in a spreadsheet format.

Quantification Res	ults							×
Time : 16:51	:29 Da	te : 1	-Jul-99	9				-
Vei Filename	ght % by SiK	Elemen MoL	t TiK	VК	CrK	MnK	FeK	
Ss_321.spc	0.67	0.54	0.54	0.16	18.01	1.68	68.52	
Ato: Filename	mic % by SiK	Elemen MoL	t TiK	VК	CrK	MnK	FeK	
Ss_321.spc	1.30	0.31	0.62	0.17	19.07	1.68	67.57	
K-R Filename	atios by SiK			iK	νк	CrK	MnK	
Ss_321.spc	0.0032	0.0039	0.00	58 0.0	017 0.	2046 0	.0165	0.1
M	atrix Co	rrectio	ns					•
Page Setup Print Results Print Spc and Results Ok								Ok

#### 7.4.1 Saving the Results

In the expanded quantification section there are three buttons that allow for the displaying (Show), clearing and saving the quantification results. Once the spectrum has been quantified the "Show" button will become enabled. The quantification results window can then be displayed and closed without re-quantifying the spectrum. The "Clear" button removes any spectrum results from the quantification window. The "Save" button allows for the saving of the quantification results as a comma separated value (.csv) file that can be opened in Microsoft Excel.



# 7.5 Quantification Options

All of the options for the calculation and display of the quantification results can be selected in the expanded quantification panel. Each of the selection buttons will display different choices below the buttons or will bring up a floating dialogue box. The four settings for Method, SEC, Type and Stds. Can be changed by right mouse clicking on them.

ZAF List	SE	с
Туре	Sto	ls
Results % Conc		
<b>Vacuum</b> High ∀ac		
Save S	how	Clear
☐ Multiple		
<sup>Quant</sup> Q	Method: SEC: Type: Stds:	ZAF EDAX Elems None
The EDAX software standard algorithm is the ZAF correction. Two other algorithms, PhiZAF and Phi Rho Z, are available as options. If more than one of the algorithms are installed, the desired algorithm can be selected by right mouse clicking on the text to the right of the Quant button.

### 7.5.1 The ZAF List

The ZAF list allows the user to deselect elements that appear in the peak ID list, but are not to be quantified as a percentage. For example, if a sample is carbon coated and a carbon peak is identified in the sample but should not be quantified it can be removed from the quantification. To access the ZAF list click on the ZAF button in the expanded quant panel. A window will now be displayed with the current ZAF list that will be used for the quantification. To remove an element click on it in the list so that it is no longer highlighted in blue. It will now be labeled on the spectrum, but not included in the quantification results.

Element List	Known Concentrations Elem Concen Setup
Ok	Cancel

Also from the ZAF list dialogue box, elements with a known concentration can be included in the quantification.

- > In the expanded quantification panel, click on "ZAF list"
- ▶ In the floating dialogue box, click on "Setup".
- Enter the number of elements with a known concentration and then click "OK".
- The appropriate number of spaces will now appear in the known concentrations list. Type the first element in the "Elem" box, type the

concentration in the "Concen" box and then press the enter button. Repeat for each of the known elements.

Deselect (click on so they are no longer highlighted in blue) the elements of known concentration from the "Elements" list. Click "OK" to exit the window.

ZAF Element List	×
Elements OK EuM GdM MgK A1K SiK SrL HgM KK V Select All	Known Concentrations Elem Concen Setup SiK 25.00 1 SiK 25.00 2 A1K 5.00
Ok	Cancel

#### 7.5.2 Type Options

The "Type" field next to the Quant button allows you to change the definition of sample type. To display the results for each element individually, including oxygen if present, right mouse click on "Type" and select Elements

-	Me	thod: 74F	
	SE	Method	×
Quant 👝	т	SEC	
<ul> <li>Elements</li> </ul>		Туре	
Öxides		Stds	
<ul> <li>Oxy. By Diff.</li> </ul>			_

Selecting Oxides from this right mouse menu will show results calculated as oxides.

\*\*\*Note: A dialogue box may appear stating that oxygen is in the peak ID list and must be removed so that oxides can be calculated. Click "Ok" and the ZAF list will appear so that oxygen can be removed.

If the oxide results are not the correct ratio of element to oxygen, the correct ratio can be entered by clicking on the "Type" button in the expanded quant panel. In the displayed Oxide Ratios box, highlight the element to be changed. Enter the new ratio in the Ratio edit box, hit the enter key and then repeat for any other elements. Click "OK" to exit the window.

ľ	🗌 Oxide	Ratios	;	×
ſ	— Ele	ment	— Ratio	_
	Mg		1.00	
	6	С	2.00	
	8	0	2.00	
	12	Mg	1.00	
	13	A1	1.50	
	14	Si	2.00	
	19	K	0.50	
✓ Normalization 100.00 % ✓ O in Chem Formula Num Atoms				
Ok Cancel				

To save the oxide ratios for future analysis, select "Save As" from the file pull down menu, change the file type to be .oxi, select a file location and name and then click "save". The file can then be opened at a later time by using the "File" "open" selection, selecting .oxi file type and then browsing for the appropriate oxide table. Ratios are saved automatically to GENESIS.oxi when the application is closed. These values will then be restored when the software is opened again. Do not save to GENESIS.oxi directly.

To calculate the Oxygen by difference select "Oxy By Diff" as the "Type" from the selection box made available by right mouse clicking on the text to the right of the quant button. When oxygen by difference is used to calculate the quant results, the oxide ratios are used to calculate oxygen by stoichiometry but the oxygen is summed at the end of the analysis table. The difference is the value given to oxygen.

## 7.6 Using Standards

Standards can be either compound standards, with many elements, or pure element standards, with only one element. In order to carry out analysis using standards, you will need to calculate intensity data from spectra taken from those standards. The intensity data is then processed in one of two ways depending upon the type of standard - **Compound** or **Pure**. The processed data from the standards is known as the "pure intensity".

## 7.6.1 Compound Standards

Compound standards are standards that have multiple elements. The standard should be a microanalysis certified sample and must be completely homogeneous. The standards element list must match the element list of the unknown sample.

To begin:

- Collect a spectrum from the standard with the same set up conditions that will be used for the unknown.
- > In the expanded quantification panel, click on the "Stds" button.
- In the standards window, select Compound. The element list will now be moved into the concentrations box. Type the concentration of the first element in the edit box and then hit enter. Repeat this for each of the elements in the sample.

🔚 Standardize - ZAF					×
<ul> <li>Method</li> </ul>			— C	onc Unit V	∕t % —
C None	Set	uр	0	Oxides	
Compound	Sav	/e	۲	Elements	
C Pure	Conc	entratio	ons		
De sus Comment		S	3iK	0.72	
Beam Current Factor	SiK	0.1	72		
	ΡK	0.0	03		
1.000	MoL	0.5	55		
	CrK	17.2	21		
RZAF SEC	MnK	1.0	51		
	FeK	70.8	30		
Ok Cancel	NiK	8.3	14		

\*\*\*Note: If two lines of the same element are in the peak list (FeL and FeK for example), the message box shown below will appear. To continue standards click okay and the software will remove one line for each of the elements that has multiple lines. To remove multiple lines manually, click cancel, update the peak ID list and then begin again.

ZAF Elen	nent List 🛛 🕅
⚠	There are multiple lines of an element in the net intensity list which will be removed unless the Z List is changed.Do you wish to continue?
	<u>Yes</u> <u>N</u> o

Once the concentrations for each element have been entered (they must total 100%), click on the RZAF (reverse ZAF) button. The pure intensities will now be displayed in the Reverse ZAF window.

	Reverse	ZAF Results	×
	Intens	sities	
	SiK	2993.85	
	PK	6533.09	
	MoL	3298.87	
	CrK	1087.97	
	MnK	1119.32	
	FeK	791.48	
	NiK	537.31	
Vse As Compound			

- > Check the "Use as Compound" selection box and then click "Ok".
- The standards data is now in memory and will be used for the quantification routine. To save the created standards table, select "Save As" in the "file" pull down menu. Select the file type .qzf (Quant Meth file), give the file a name and then click save. The file can be opened later, using "File" "Open". (If the file is not saved in this manner a default file genesis.qzf will always be saved. However, the default file will get overwritten if the standards are changed)

If the standards that were used were oxides (element with oxygen in stoichiometric quantities) they can be set up as standards starting in the same way that a compound standard is created. In the Standardize ZAF dialogue box, switch "Conc Unit Wt%" in the upper right hand side from elements to oxides. Enter the weight percentage of each element oxide in the Concentrations Edit box and then proceed as before for a compound standard.

### 7.6.2 Pure Element Standards

Pure Element Standards can be used to build a pure element intensity table to be used in quantification.

Spectra can be collected for a group of pure elements of interest. The same conditions must be used for the collection of each of the pure element standards and the unknown. Ideally, the beam current will be measured using a Faraday cup between each collection.

With the pure element spectra collected, begin setup by expanding the quant portion of the main panel and clicking on the standards (Stds) button. Select "Pure" in the "Standardize ZAF" window. Click on "Setup". The intensity data for the pure element is then derived from the spectrum and the measured box is updated to show the intensities. Click on the "Save" button in the window. A message will appear confirming the change of the pure intensity value. Click "Yes" to continue.

Repeat the process for each of the pure element standards that are to be used. Once all of the standards have been entered they can be saved together as a standards file. Check that all of the elements that have been measured on a standard are updated by clicking on "Factors". This button will be available when the "Stds: Pure" is shown in the quant panel. The Pure Element Intensities dialog box that is displayed can be used for viewing or manually editing the values:

Pure Element Intensities				
Voltage 15.00 Tilt 0.00	X-Ray Shell			
Take-off 35.00	K 1.00			
Detector Type Standard 💌	12 Mg 1551.13 A 13 Al 1503.30 14 Si 1374.06 15 P 1.00			
Method ZAF 👤	16 S 1.00 17 Cl 1.00 18 Ar 1.00			
Ok Cancel	19 K 1.00 🔽			

To save the standards data use the File "Save As" menu item, switch the file type to .std, browse for a desired location, select a file name and click the "save" button. If the file is not saved in this manner a default file genuser.std will be automatically saved.

The Beam Current Factor can be used if there is a fluctuation in beam current between the collection of the standard and the unknown. Using a beam current monitor, calculate the ratio of the beam current used for the standard and the beam current used for the unknown or the other standards. In the expanded quantification panel, click on the "Stds" button. In the displayed window enter the ratio in the Beam Current Factor box that is in the Standardize ZAF window.

## 7.7 SEC Factors

"Standardless Element Coefficients" are used to customize the standardless analysis to a particular detector's characteristics.

To maximize the quality of the results, the same accelerating voltage, matrix type and set of elements should be used for the standard and the unknown. Using the standard, collect a spectrum and identify all of the elements.

-	SEC F	actors		×
Г	- SEC	CTable -		
	ΘE	DAX	O User	
Γ	X-Ra	y Shell -		
		۰R	OL OM	
		Eleme	nt Factor	
		Cr	1.00	
	18	Ar	1.00	
	19	K	1.00	
	20	Ca	1.00	
	21	Sc	1.00	
	22	Ti	1.00	
	23	V	1.00	
	24	Cr	1.00	-
	Ok	Can	cel Advanc	ed

In the expanded Quant portion of the main panel, click on the "Stds" button. Select "Compound" and then click on the "Setup" button. Type the known percentages for each element. (Press the enter key after each entry). Click on the SEC button at the bottom of the window. Check the Update SEC table box and then click "OK" to close the window. To view the current SEC settings click on the SEC button in the expanded Quant portion of the panel. The new factors will only be used when the SEC selection is set to "User" by right mouse clicking to the right of the Quant button and selecting user SECs. The SEC table can be saved with a particular name so it can be used for similar samples at a later time. Select "Save As" from the file pull down menu. Select .sec as the file type, select the desired location, give the file a name and click "save".

To recall an sec file, select "Open" from the File pull down menu. Switch the file type to \*.sec and browse for the desired file. To the right of the quant button the text will update to show that a user SEC table is being used.

### 7.8 Other Quantitative Techniques

Another technique, carbon coating correction with light element adjustment factors, is available in the spectrum tab for optimizing the quantitative analysis.

#### 7.8.1 Coating Correction

Coating correction can be added for samples that are coated with carbon. It can be used when the EDAX SEC factors are enabled. To add a carbon coating correction, open the SEC dialogue box by clicking on the SEC button in the expanded quantification window. Click on the "Advanced" button. Enter a value for the coating thickness and then hit enter. The primary purpose of the coating correction is to compensate for absorption of low energy x-rays such as oxygen by the carbon coating. The thickness setting ranges from 0 to 20 and the value should be iterated until the optimum correction is obtained. A known compound (Si0<sub>2</sub> for example) can be used for determining the correct coating value. This value can then be applied to other spectra collected on the same sample.

Advanced Standar	dless Adjustmer	its 💌	1	
Coating Correc	tion			
Element	c 🔽			
Coating Factor	14.0			
Light Element Adjustment Factors				
B 110.00	C 130.00	N 8.00		
ОК	Cance	1		

## 7.8.2 Light Element Adjustment Factors

Light element Adjustment factors can be used to improve the standardless quantification results for samples with boron, carbon and nitrogen. The light element adjustment works similarly to the SEC factors, but are scaled differently. In the "Advanced" SEC window, the three values can be adjusted by highlighting an old value and then typing the new value into the edit box. To reduce the amount of an element, reduce the adjustment factor. Adjust the factor until the quantification results are optimized.

# 7.9 Variable Pressure Quantification

The Variations in Pressure (ViP) module is available as an add on feature. This will correct for beam scattering that occurs while working in low vacuum conditions.

In a regular SEM the good vacuum conditions ensure the primary electron beam can reach the specimen without encountering any gas molecules. However, in a low vacuum SEM part of the electron beam will scatter due to the gas molecules, thus increasing the size of the area of impact on the specimen (skirting effect). In the pressure variation method, x-ray data are collected at two different pressures and the sample composition is calculated by extrapolating the x-ray intensities to zero pressure. For the most accurate results the two pressures should differ by a factor of two. It is recommended to keep the pressures in the range of 0.1 to 1.0 Torr. At higher pressures the results may not be as reliable because the intensity is no longer a linear function of pressure.

To use the Variations in Pressure feature, click on the Vacuum button in the expanded Quantification Panel.

ZAF List	PEI
Туре	Stds
Results	% Conc
Vacuum	Low Vac
O Hi Vac ⊙ I	Lo Vac
A: Torr	A>B B:
Save S	how Clear
🗖 Multiple	×
<sup>Quant</sup> Q	Method: ZAF SEC: Pure Type: Elems Stds: Pure

When the **Hi Vac** radio button is on, pressure variation calculations will not be performed and the **Quant** button refers to normal operation and the Editbox for the **A:** pressure value is disabled. If the Hi Vac button is clicked after having done Low Vac calculations, then the current spectrum, the overlay and the pressure values will all be cleared.

When the Lo Vac radio button is clicked the pressure edit box A: is enabled and ViP calculations can be performed.

The procedure for using the Variations in Pressure feature is as follows:

- 1. Select the Low Vac radio button.
- 2. Acquire a spectrum in memory A (or open a file).
- 3. If there are no peaks identified, or if the peak list needs to be changed, this should be done now by going to the Peak Id Panel. The peak list for the A and B spectra must be the same for ViP calculations to work correctly. If the two peak lists are not the same when the Quant button is clicked, an error message will be displayed:

WARNING	I
Peak list for the two pressures is not the same.	
Do you want to continue with the peak list from Spectrum B?	
Yes No	

It is recommended to collect the high pressure spectrum first as it might contain a greater variety of peaks.

- 4. Type in the pressure value in the edit box A: and hit the Enter key.
- Press the button A>B. This button will become active after the pressure is entered in
   A: The spectrum will be transferred to memory B and is displayed as an outline
   similar to an overlaid spectrum. The pressure, entered in A, is transferred to B as "read
   only". The pressure is automatically written into the label of the spectrum and the
   Pressure A: editbox is cleared.
- 6. Acquire a new spectrum in A (or open one from file).
- 7. Type in the pressure in the editbox A: and hit enter. The pressure value will again be added to the spectrum label. The Quant button will be enabled now (was grayed out until this moment). Multiple measurements is always grayed out (not possible under Low Vac conditions).
- 8. Press the Quant button and the results will be displayed.

The units for the pressure values can be changed by right mouse clicking on the text that displays the current unit.

The ViP procedure for analyzing spectra collected in low vaccuum conditions is very similar to the published work of Doehne (1996, Scanning, vol. 18, p. 164-165; as well as 1997, Scanning, vol. 19, p. 75-78) and Bilde-Sorensen and Appel (1996, Abstracts of 48<sup>th</sup> Annual Meeting of the Scandinavian Society for Electron Microscopy, SVF, Aarhus, Denmark). For additional information on low-vacuum analysis please refer to the works of these authors and their subsequent publications.

## 7.10 The Match Option

The EDAX spectral matching program can be used for comparing spectra to a saved set of reference spectra. The Match option must be installed to activate this feature. Match can be used during data collection.

In order to use Match:

Select "Match" in the "Setup" pull down menu. From the opened dialogue box, open the desired match file by clicking on the "Match File" button and browsing for the file.

Once the file is open, a "Threshold" and "Match Factor" value can be given. The threshold allows the user to adjust the sigma threshold value (how close a spectrum must be to the library spectrum to be considered a match). The match factor is the importance of each element in the ID list to the match. This gives the user the ability to have the fit of particular elements be more influential in the total fit, or not considered at all. For all elements to be considered equally, each should have a weight factor of one hundred, which is the default setting.

When the setup is complete, click "Ok" and then check the "Match" option displayed in the expanded Quant panel the "Results" button is clicked.

When a spectrum is collected and quantified, the results of the match will appear at the end of the quantification results table. All of the results that are within the threshold will be given. If spectra are being displayed as multiple results, the best fit standard will be given for each spectra.

# 8 AUTO SPECTRUM PROCESSING

The auto spectrum processing mode allows for the automatic collection or processing of spectra. The collection mode includes options for collection setup, saving and printing.

## 8.1 Auto Collection Setup

In the "Auto" pull down menu select "Setup". From the displayed window select the settings that are to be used for the collection.

🖬 Auto Spectrum 8	🛾 Results Setup 📕
- Preset	
<ul> <li>Live 100</li> </ul>	sec
O Clock	sec
C Counts	cnts
Peak ID	Background
<ul> <li>Auto</li> </ul>	<ul> <li>Auto</li> </ul>
C Current	C Current
Printed Output	Results
Results	🗷 Save To File
Spectrum	• .CSV • .DAT
Spectrum Save Filename	gapagia
	genesis
Ok	Cancel

The settings are as follows:

Preset: Defines the spectrum collection length. The preset can be set for any number of live or clock seconds or until the enabled ROI(s) reaches the set number of counts. Select the option using the appropriate button and then type the desired time (or number of counts) into the edit box.

Peak ID: Select between the current peak identification list or have an automatic identification performed for each spectrum.

The Background drawn for each of the spectra can be the spectrum currently displayed on the screen (choose current) or, an automatic background can be performed for each spectrum (choose Auto).

Print Output: The spectrum and/ or the results can be printed automatically. Select one, both or none of the Printed Output selections boxes. The printout will show the spectrum displayed at full scale value and as defined in the Page Setup dialogue box. (accessed through the "File" pull down menu.)

The quantitative results can be saved as either a .csv file or a .dat file by checking the "Save to File" box in the Results section. (Leave this unchecked to not save the results.) The name and location will be determined by the name and location of the saved spectrum, or into the default location if a specific location is not selected.

The spectrum file can be saved automatically by checking the "Save" box in the spectrum portion of the window. Use the "Filename" button to browse for a location and enter a specific name. Click on "save" to close the window.

Click OK to close the set up window.

## 8.2 Auto Spectrum Collection

Once the set up is complete, the automatic collection can be started.

To start the collection, select "Start" from the "Auto" pull down menu. The spectrum will collect and be saved and printed as set up in the Set up window.

To stop the collection before it has finished, select "Stop" from the "Auto" pull down menu.

To start a second analysis, open the "Setup" window, select a new file name (and location if desired), click OK to close the set up window and then start the second auto run. ("Start" in the "Auto" pull down menu. )

## 8.3 Processing Spectra from Disk

Up to 9,999 previously collected spectra can be processed. Each spectrum is read from disk and a new element list and background fit can be applied if desired. The quantification results are written to a single \*.Csv file.

To access the process set up window, select "Process Spectra" from the "Auto" pull down window. In the top left window browse for the folder that contains the spectra of interest.

Process Spectra From Disk			X
Choose Files c:\img\usr\sample1\stub01\spc		Spectra to Process 414	
[-t-] [-v-] [-w-] [-y-]	Add >>       Remove       Clear All	00010001.spc 00010002.spc 00010003.spc 00010004.spc 00010005.spc 00010006.spc 00010007.spc 00010008.spc	
Peak ID		Background ———	Speed
C Auto C File	Current	Auto C File	0.1 to 10
O Auto ID First Spectrum Only	С	Current	,2 sec.
── Output File ── C:\DocWork\ReCalc\Example1.C I Extended Data Report	SV		File
Ok		Process	

Highlight the spectra (click on the first, ctrl click on other individual spectra, or shift click on the last spectrum in a consecutive list) that are to be processed. Click on "Add>>" to move the spectra into the "Spectra to Process" box. The total # of spectra will be displayed.

Select the desired Peak ID and background processing option. The current background and peak ID can be used (select current) or the saved background and Id can be used from each individual file (File). There is also an option for an Auto peak Id for the first spectrum that will be used for all of the other processed spectra.

Click on the button in the "Output file" field to select a name and browse for the desired file output location. The results will be saved as a csv file with the selected name. Click on "Save" to close the window.

Click on the "Process" button in the in the "Process Spectra from Disk" window to begin processing the spectra.

#### 8.3.1 Extended Data Report

Often spectral data is colleted in other software tabs ( like Particle & GSR), and because of the large #'s of spectra it would be nice to process them as a batch, yet maintain all the quantitative data in a single CSV file. <u>This mode is only supported for SEM Quant ZAF quantitation</u>. It can handle up to 28 elements per spectra, which output a CSV file that is 254 columns wide.

During the spectral reprocessing in this mode, the Genesis application window will minimize after each 1000 spectra to conserve windows resources.

The output format per output each ROW in extended data report mode is :

Spectrum Name, Live Seconds, WT% for all Elements, AT% for all Elements, K-Ratio for all Elements, Net Intensity for all Elements, Background Intensity for all Elements, Intensity Error for all Elements, Z-Term, A-Term, F-Term

# 9 TEM MATERIALS OPTION

TEM Quantification methods include:

- Materials (TEM Quant Materials)
- Biological (TEM Quant Biological).

This chapter describes the Materials methods. See Chapter 10 for Biological methods. Only the options that have been purchased with the system will be active and others will display as disabled items.

To Access the TEM Quant Materials option, select "Mthin" by right mouse clicking on the text to the right of the Quant (Q) button. From the selections for "Method" choose Mthin. The main panel will now be updated to show the appropriate buttons. Switching to the Mthin option will change the expanded Collect panel and the Quant panel. The concentration background option will be removed from the expanded background panel.

## 9.1 Quantification: TEM Materials Methods

In the main spectrum panel expand the Quant section. The displayed panel will have the quantification options for Mthin as shown here.

	Z List
	Туре
	K Factor
	Corrections
	n 🔽 Inten 🔲 Match s 🔲 Fluor 🔲 Ionic
Save	Show Clear
🗖 Multip	ole 🗙
Quant	Q Method: MThin Type: Elems KFactor: Theoret Correction: Thin

### 9.1.1 Z List

Clicking on the **Z** List button in the expanded Quant panel allows for selection of the elements to be included in the quantification process. This dialog box allows you to select all elements for quantification calculations. Normally, the quantification element list is determined by the peak id list. Therefore, you may never need to modify this quantification element list.

If the peak id list contains multiple lines of one element, the quantification calculations normally remove one of the lines from the list. However, if you want to retain the peak id list, without having the quantification ignore multiple lines of an element, the quantification element list must be set manually.

To retain all of the elements and lines, click on **Select All**, then **OK**. To select only some of the elements, deselect those elements in the list that should not be included in the calculations. The quantification element list must be a subset of the peak id list, so only deletion of elements is allowed. Only those elements selected when **OK** is clicked will be in the quantification element list.

To reselect all elements of the peak id list for the quantification element list, you click on **Select All** in the dialog box. Once you are satisfied with the quantification element list, you click on **OK**.

To cancel any changes made, you click on **Cancel** and the dialog is dismissed. The quantification element list remains as you selected it until a new peak list is chosen in the **Peak Id** control window or another spectrum with a different peak list is read in from disk.



### 9.1.2 Type (Elements, Oxides, Oxy by Diff)

Right mouse click on the "Type" text next to the Quant button to select between Elements, Oxides or Oxygen by Difference for the quantification calculations.

Select the desired type from the displayed list.



- Elements: Click on **Elements** if the sample is known not to contain Oxygen, or if Oxygen has been included in the element list during element identification.
- Oxides: Click on **Oxides** if oxygen is known to be present in stoichiometric quantities in the sample, eg, minerals. The oxide concentration in particular elements will be expressed in the results as the oxide% for that element.
- Oxy. by Diff.: Click on **Oxy. by Diff.** if Oxygen is known to be present but has not been included in the element list during identification, and if the stoichiometric quantity of oxygen is not known. This can only be used if standards are employed.

The percentage of the identified elements in the sample is calculated and subtracted from 100 percent. The difference represents the amount of Oxygen in the sample.

Ratios: The **Type** button in the expanded Quant panel refers to the **Oxides** option and brings up the Oxide Ratios box. It allows you to review or edit the oxide ratios of identified elements.

-	Oxide	Ratios	;	×
Г	— Ele	ement	— Ratio	
	6	С	2.00	
I	8	0	2.00	
	12	Mg	1.00	
	14	Si	2.00	
I	20	Ca	1.00	
	26	Fe	1.50	
		in Che Num A	m Formula toms	1
		)k	Canc	el

Editing a ratio

To edit a ratio:

- 1. Highlight the ratio to be edited.
- 2. Highlight the value to be changed.
- 3. Type in the new value.
- 4. Press Enter to save the new value before making further changes.

The new value is entered in the list.

Click on **OK** when all editing is complete.

#### **Num Atoms**

This allows concentration calculations of minerals to be performed with all elements ratioed to Oxygen, with the user specifying the number of atoms of oxygen in the formula.

**Num Atoms** becomes active when Oxygen is measured, or if it is calculated using Oxygen by difference. The atomic concentration column is replaced by a CHEM column.

F	Oxide	Ratios		×
ſ	— Ele	ment	— Ratio	
	6	С	2.00	
	8	0	2.00	
	12	Mg	1.00	
	14	Si	2.00	
	20	Ca	1.00	
	26	Fe	1.00	-
		in Che	m Formula	
			toms 4	
	C	)k	Can	cel

As an example, if you suspect that the sample being analyzed is an Olivine, (Mg,Fe)<sub>2</sub>SiO<sub>4</sub>, enter 4 in the dialog box.

_	Quantification Re	esults			×
				Label :Nist 2063 : 29-Jan-1998	a CM200u 🔺
	Thin Apx Theoretical	KAB, Oxygen	By Diff., M	lodel : Zaluzec	
	Element	Weight %	Chem		
	СК	8.8	0.9		
	MgK SiK	4.1 13.9	0.2		
	CaK FeK	6.0 6.4	0.2 0.1		_
	•				
	Page Setup	Print Results	Print Spo	and Results	Ok

After quantification, the results will be as above, with the **Chem** column confirming the chemical formula. - in this case, (Mg. Fe):  $a SiQ_{4}$ 

 $(Mg, Fe)_{1.9}$  SiO<sub>4.</sub>

Saving oxide ratios under a new file name

To save oxide ratios under a user-defined file name:

- 1. Select File from the Windows Menu bar.
- 2. Click on Save As.
- 3. Scroll down the Save File as Type menu.
- 4. Highlight Oxide Table Files (\*.oxi).

A list of available .oxi files displays in the default user area

- 5. Enter the name of the .oxi file to be saved, eg, minerals.oxi.
- 6. Click on OK.

Ratios are saved automatically to GENESIS.OXI when you quit the application. These values are restored the next time the application starts. Do not save to GENESIS.OXI directly.

### 9.1.3 K Factor

The **K Factor** button in the expanded Quant panel allows you to review or edit the K Factors to be used in the quantification calculation. The currently selected K Factor is displayed in the text next to the Quant button.. To change the K factor method:

1. Click on **K Factor** button. The **KAB Factors** panel will appear as shown below.

ZL	ist
Тур	e
K Fac	tor
Correct	ions
Theoretical EDAX	Standards User

Theoretical K Factors - Standard Models

To use the theoretical K factors click on the **Theoretical** button in the KAB portion of the panel. The **Cross Section Model Window** appears. Choose the desired model from the scrolling list.

Cross Section Model	×
Model	
Zaluzec 💌	
b Term 1.00	
c Term 1.00	
Ok Cancel	

Theoretical K Factors - User Model

- 1. To use the theoretical K factors with user-defined b and c coefficients, click on the **Theoretical** button in the KAB portion of the panel. The **Cross Section Model** window appears. Choose **the User Defined** option from the scrolling list.
- 2. Enter the values of b and c that you want to use in the **b Term** and **c Term** fields and click **OK**.

Cross Section Model	×
Model	
User Defined 💌	
b Term 1.23	
c Term 0.78	
Ok Cancel	

Experimental KAB Factors - EDAX Set

To use the EDAX set of experimental KAB factors:

Click on the **EDAX** button in the **KAB** portion of the panel. **The KAB Factors** window appears. These settings cannot be edited however you can click on the **User** radio button in the **Table** panel to show and edit the **User** set.

KAB Factors						X
_ Table	ſ	— X-Ra	ay She	ell —		
● EDAX O User		Θĸ	Eler	nent	Fac	tor
Voltage 200.0		ΟL	K		1.210	0
Det. Type Standard 💌		13 14	Al Si		.250 .000	
O Open O Closed			Р		.040	
🗖 Sapphire		16	ន C1		.060 .060	
Coshhune		18	Ar	_	.060	
Ok Cancel		19	K	1	.210	<b>-</b>
		,				

#### Experimental KAB Factors - User Set

To use the user set of experimental KAB factors:

- 1. Click on the **USER** button in the **KAB** portion of the panel. The **KAB Factors** window appears.
- 2. To edit values, highlight the existing entry for the chosen element in the scrolling list.
- 3. Edit the value in the Factor field.

4. Click on **OK** when finished editing.

KAB Factors		×
_ Table	- X-Ray Shell	
C EDAX C User	● K Element Factor	
Voltage 200.00	OL K 1.210	
Det. Type S UTW 💽	13 Al 1.250 A 14 Si 1.000	
O Open O Closed	15 P 1.040	
🔽 Sapphire	17 Cl 1.060	
	18 År 0.960 19 K 1.210 ▼	
Ok Cancel		

#### Calculating KAB Factors - With Standards

KAB factors can be calculated by the theoretical method or derived from measurements with real standards.

To use standards to generate experimental KAB factors:

1. Click on the **Standards** button in the **KAB** portion of the panel. The **Standardize** window appears:

🔲 Standardize	×
Calculate KAB	
<ul> <li>With Standards</li> </ul>	Concentrations
C Theoretical KAB	C K 7.00
Scale Element : 📃 👻	СК 7.00 🔺
	MgK 6.00
Calculate	SiK 40.00
	CaK 20.00
	FeK 12.00
	Cut 15 00
Ok	Cancel

As the window loads, a net-intensity calculation is performed on the current spectrum using the current element list, background methods and background points.

2. Click on the With Standards radio button.

- 3. Choose from the **Scale Element** scrolling list the element to be the reference element (usually Si).
- 4. Highlight each element in the scrolling list in turn and enter its concentration in the **Concentrations** field. There are two methods to calculate KAB factors in this window.
- 5. Click on the **Calculate** button and the current net intensities will be used to calculate experimental KAB factors. The results of the calculation will appear in **Calculated KAB Factors** window

Any or all of these values can be used to update the current user KAB table. To do so:

1. Click on the User radio button to display the user KAB factors. The scrolling list will display the calculated values from the standard alongside the current KAB user factors.

	Calcul	ated KAB Fa	actors	×		
	— KAB	3 Table 👘				
	O ED.	AX @	User			
		Calc'd —	Current -	_		
	C K	0.84	1.00			
	MgK	0.50	1.81			
	SiK	1.00	1.00			
	CaK	1.27	1.05			
	FeK	1.01	1.35			
	CuK	0.87	1.51			
	CuK	0.87	1.51			
Update KAB Table						

- 2. Highlight the elements whose KAB factors you want to update.
- 3. Click on the Update KAB Table check box.
- 4. Click on **OK** when finished updating.

Calculating KAB Factors - Theoretical Method

To use KAB factors from theory:

Click on the **Standards** button in the **KAB Factor** portion of the panel. The **Standardize** window appears:

🖬 Standardize	×
Calculate KAB Vith Standards Theoretical KAB Scale Element : OK  Calculate	- Concentrations SiK 24.6
Ok	Cancel

- 2. Click on the Theoretical KAB radio button
- 3. Click on Calculate and the Calculated KAB factors window will appear.

Any or all of these values may be used to update the current user KAB table. To do so:

1. Click on the User radio button to display the user KAB factors. The scrolling list will display the calculated values from the standard alongside the current KAB user factors.

E	Calcula	ated KAB Fa	ctors	×		
	— KAE	) Table 👘				
	O ED/	4X @	User			
		Calc'd –	Current -			
	ОК	1.00	1.00	•		
	NaK	0.51	3.97			
	SiK	0.50	1.00			
	K K	0.54	1.21			
	CaK	0.55	1.05			
	TiK	0.68	1.14			
	CuK	0.91	1.51	-		
Update KAB Table						

- 2. Highlight the elements whose KAB factors you want to update
- 3. Click on the Update KAB Table check box.
- 4. Click on **OK** when finished updating.

#### Saving KAB Factors permanently

It is possible to use different sets of KAB factors for different analytical conditions and sample element matrices. The factors are stored in .KAB format files.

By default, the EDAX and User KAB factors are stored in GENESIS.KAB in C:\EDAX32\MTHIN.

You can also store KAB factors in other KAB files. The default location for other user KAB files is D:\EDAX32\MTHIN\USR.

To save KAB data in files other than GENESIS.KAB:

1. Select File from the Windows menu bar.

Save As		?	×
Save in:	🔁 Usr 💽 📃	<b>*</b>	
File <u>n</u> ame:	Stainles	<u>S</u> ave	
Save as <u>type</u> :	Standard Files (*.std)	Cancel	

- 2. Click on Save As.
- 3. Select KAB Table Files (\*.kab) from the Save as type drop down.
- 4. Select an existing KAB file or create a new file name, with the extension .kab.
- 5. Click on OK.

#### 9.1.4 Corrections

The **Corrections** button in the expanded portion of the Quant panel allows you to review or edit the matrix corrections to be used in the quantification and the type of results required. The current results type is written to the right of the Quant button.

1. Click on the Corrections button. The expanded panel now displays:

Z List
Туре
K Factor
Corrections
n 🔽 Inten 🗖 Match s 🔲 Fluor 🗖 Ionic

### <u>Thin</u>

If the TEM specimen is very thin, there is no need to allow for the matrix effects of absorption or fluorescence.

**Note**: The thickness at which the specimen can be considered to be "thin" depends on microscope kV and the composition of the specimen

If the specimen can be treated as "thin", click on the **Thin** check box. Checking **Thin** will automatically disable the **Abs** and **Fluorescence** check boxes.

#### Not Thin

If the specimen is sufficiently thick to require an absorption correction, click the **Abs** check box.

Similarly, if elements in this specimen fluoresce each other, click on the **Fluorescence** check box.

In order to calculate the absorption and/or fluorescence correction, specimen thickness and specimen density should be known. If the density is not known, the average density will be calculated.



If either **Abs** or **Fluorescence** has been checked, the **Abs. Conditions** window will appear when performing the quantification calculation:

At this point, you should enter the values of thickness and density.

If the Ionic checkbox has been checked, then the Ionic Abs. Conditions window will appear when performing the quantification calculation:

You may enter valences for each element and the thickness will be calculated using these values.

lonic Abs. Conditions	×
X Tilt : 35.00	Deg
Y Tilt : 90.00	Deg
Density : 0.00	gm/cm^3
Valences 8 0 -2 <b>11 Na + 1</b> 14 Si + 4 19 K + 1	
Element Valence Na + 1	
Ok Ca	ancel

The Ionic Compound Method of Van Cappellen and Doukhan<sup>1</sup> uses the stoichiometry of chemical compounds to determine the mass thickness of the specimen. The method is based on the charge balance in a compound. The number of cation atoms multiplied by their valence must equal the number of anion atoms multiplied by their valence. Using this knowledge, the atomic concentrations can be calculated with a trial value of the mass thickness. Several trial mass thicknesses can be applied, the results plotted versus mass thickness, and the crossover point observed.

In order for the method to be successful, the K Factors of the elements must be accurately known. It is advisable only to apply this method with measured k-factors.

<sup>&</sup>lt;sup>1</sup> E. Van Cappellen and J.C. Doukhan, Ultramicroscopy 53 (1994) 343-349



Clicking OK will then calculate the thickness and plot the results.

You can then elect to accept the thickness calculated, enter another thickness or cancel the operation entirely. If the thickness is entered or accepted the concentrations will be calculated and the results presented.

### 9.1.5 Starting quantification

Once you have made your changes to the fields in the expanded quant panel, you can start quantification. To do so:

1. Click on the **Quant** button in the main panel.

The Quantification Results window displays:

Quantification		)_gls.spc l	abel :Glass CM2.	× 00ut Spot ×				
Thin Apx,	Acquisition Time : 17:19:47 Date : 29-Jan-1998 Thin Apx, Abs Corr Theoretical KAB, Elements, Model : Zaluzec							
	Weight %	•	Xpt					
0 K	28.4	47.3	0.002					
NaK SiK	2.3 34.3	2.6 32.5	0.001 0.000					
K K CaK	3.4 7.6	2.3 5.1	0.000 0.000	_				
•								
Page Setup	. Print Result	s Print Spc	and Results	Ok				

All the data specified for display in the page-setup options are listed and accessed by scrolling.

You can now change the format in which results are displayed by pressing the **Page Setup** button and specifying the new format.

🔽 Filename	🔽 Date and Time
🔽 Label	Spectrum
Parameters	C Current
🔽 Spectrum	
🔽 Count Status	Outline Mode
✓ Border	🔽 Overlay
✓ Axis/Grid	Deconvolution
Element Markers	🔽 Background
🖸 Color 🛛 🔿	Black and White
Quantification ——	
Multiple Results	🔽 At % 🔽 Wt %
77-77	🗹 K Ratio 🛛 🗹 ZAF
Margins	
Top : 1.00 in	Left : 1.00 in
Font Courier Ne	w Default
Oĸ [	Cancel

To print the results of the quantification calculation:

Click on the **Print** button in the **Quantification Results** window. Click on Print Spc and Results to get both the spectrum and the results on one page.

#### 9.1.6 Results Options

After you have obtained your quantification results, you have four options in the expanded quant panel:

- Save
- Show
- Clear
- Concatenate results (multiple checkbox displays elements top left to right, with spectra names in left-hand column)

#### Save

The Save option allows you to save the quantification results to disk. To do so:

1. Click on the **Save** button.

Save As					? 🗙
Save <u>i</u> n:			•	← 🗈 📸 🎟 ▼	
My Recent Documents Desktop					
My Documents My Computer My Network Places					
T Idees	File <u>n</u> ame: Save as <u>t</u> ype:	Stniss.csv Comma Sep Val (*.csv)		•	<u>S</u> ave Cancel

The standard Windows save options appear.

You can save results in two file formats:

- Comma-separated values (.CSV files)
- Binary format (.DAT files).

CSV files are in ASCII format and compatible with spread-sheets and word processors.

DAT files are a compact binary format, compatible with EDAX software.

#### Show

The Show option is used to redisplay the Quantification Results window.

Clear

The Clear option clears the Quantification Results window.

#### Concatenate results (multiple)

If you are carrying out multiple analyses, check the **Multiple** option. The results of the current quantification and any subsequent results will be concatenated:

- In the Quantification Results window, and
- In the specified file, each time **Save** is selected.
# **10 TEM BIOLOGICAL OPTION**

TEM Quantification methods include:

- Materials (TEM Quant Materials)
- Biological (TEM Quant Biological).

This chapter describes the Biological methods. See Chapter 9 for Materials methods. Only the options that have been purchased with the system will be active and others will be displayed as disabled items.

To Access the TEM Quant Biological option, select "Bthin" by right mouse clicking on the text to the right of the Quant (Q) button. From the selections for "Method" choose Bthin. The main panel will now be updated to show the appropriate buttons. Switching to the Bthin option will change the expanded Collect panel and the Quant panel. The concentration background option will be removed from the expanded background panel.

## 10.1 Quantification: TEM Biological Methods

The expanded BThin quantification panel is shown below:

	Z List	1
	Results	j –
	Grid Params	j
	S Factors	
	Water Method	j
	Save Show	
		X
-	Method: BTh Results: Grid	
Quant	O Type: Grid	ł
_	SFactor: ED. Water: Hydr	

The main difference between the calculations used in Material Thin and those in Biological thin lies in the use of the peak-to-background intensity ratio.

Here, background means the continuum intensity corrected for extraneous components

resulting from X-ray scatter from outside the analyzed volume. If the intensity ratio is used, the calculation of concentration will be independent of specimen thickness.

Biological specimens consist mainly of an organic matrix of elements, C, N, O and H, which are not generally detectible using conventional EDS methods - standards are usually needed. Additionally, mass loss and rough surfaces are much more common problems with biological specimens, so a method of calculating concentrations which is independent of specimen thickness will lead to more accurate concentration results.

In order for the intensity ratio method to be used, it is first necessary to measure grid and film spectra. A standards file of S factors must also be created before similar unknowns can be analyzed routinely.

With Biological thin, it is also possible to determine the local water content in biological tissues. Three different methods fit most practical cases:

- 1. Measuring the sample in a frozen-hydrated state and freeze-dried state, without knowing the concentration values.
- 2. Directly measuring the oxygen concentration in these two states, using an ECON detector.
- 3. Measuring the sample in a freeze-dried state only, but with a standard.

## 10.1.1 Background

The Background Panel looks the same as the one in SEM methods except that the concentration background method is not available. *Note that although the visual display is the same the underlying background calculation methods are different.* Refer to section 7.2 for usage of the background panel.

## 10.1.2 Results

The **Results** button in the expanded Quant panel allows you to choose the information to be displayed following spectrum quantification:

- Grid/Film/Sample Continuous and Peak Intensities
- Concentrations
- Water Calculations
- Match (if installed).

## Selecting result type

To select one of the available results types:

1. Expand the Quant section of the main panel. Click on the **Results** button.

The following choices will now be displayed in the expanded panel:

	Z List
	Results
	Grid Params
	S Factors
	Water Method
🔽 Grid	
🗖 Con	c 🗖 Water 🗖 Match

The Sample checkbox may display Grid, Film or Sample depending on the Sample Type selected.

2. Click on the result type or types to be displayed.

## 10.1.3 Sample Type

The **Sample Type** can be changed by right mouse clicking on the "Type" text next to the Quant button. To select the sample type:

1. Right mouse click on the text to the right of the Quant button.



2. Select the sample type

3. Click on the Grid Parameters button to change grid parameters.

🔲 Grid Para	meters		×
Grid N	vlaterial ———		1
	Material	Ni	
Start Ke	eV : 7.38	End KeV : 7.57	
— Contin	uous Region –		
Start Ke	eV : 4.20	End KeV : 6.20	
(	ж	Cancel	

4. Click **OK** to accept the values displayed in the **Grid Parameters** Dialog box.

## 10.1.4 S Factors

To select S factors:

- 1. Right mouse click on the text to the right of the Quant button.
- 2. Select the set to be used.



The chosen set of S Factors is displayed if you click on the S Factors button in the expanded quant panel.

S Factors	
Table	- X-Ray Shell
EDAX     User	С <sub>К</sub> Element Factor
Voltage : 200.00	
Voltage : j 200.00	21 Sc 1.000 🔺
	22 Ti 1.000 🛁
	23 V 1.000
	24 Cr 1.000
	25 Mn 1.000
	26 Fe 1.000
OK Cancel	27 Co 1.000 💌

The S Factors window is divided into two fields:

- Table
- X-Ray Shell.

## Changing S Factor tables

To change the currently selected S Factors table:

1. Click on EDAX, or User.

**EDAX** is a read-only table, and can be used for analysis at any accelerating voltage. **User** is an editable, user-defined table of factors.

## X-ray shells

The X-ray shells section allows you to:

- Select X-ray shells
- Review the factors relating to each shell.

To select an X-ray shell:

1. Click on the K or L button.

To edit the factors in the User set:

- 1. Select User in the Table panel.
- 2. Highlight the element to be edited in the scrolling list
- 3. Edit the S Factor value
- 4. The highlighted element and its factor display in the fields above the element list.

## Saving User S factors

After you have made changes to S Factor values in the S Factors window, you can save them permanently to disk, either under your own file name in the default user area (D:\EDAX32\BTHIN\USR) or automatically in C:\EDAX32\BTHIN\GENESIS.SFT when you quit the application. Do not save values manually in GENESIS.SFT.

To save S Factors under a user-defined filename:

Save As				? ×
Save jn:	🔄 Bthin	- (	1	0-0- 5-5- 0-5-
🛋 dxedax.sft	My Computer			
	📼 3½ Floppy (А:) 📷 (С:)			
	🚞 Edax32			
	🖶 <mark>Bthin</mark> ᇊ (D:)			
	🥃 (E:)			
l	🗳 (F:)	•		
File <u>n</u> ame:	dxedax.sft		_	<u>S</u> ave
Save as <u>t</u> ype:	S Factor Table Files (*.sft)		•	Cancel
			_	

- 1. Select File from the Windows Menu bar.
- 2. Click on Save As.

- 3. Scroll down the Save File as Type menu.
- 4. Highlight S Factor Files (\*.sft).

A list of available .sft files displays in the default user area

- 5. Enter the name of the .sft file to be saved, e.g., good.sft.
- 6. Click on **OK**.

#### Calculating S Factors - With Standards

S Factors can be derived from measurements with real standards.

To use standards to generate experimental S factors:

1. Click on the **Water Method** button in the expanded **Quantification** panel. The panel updates to display:



2. Click the **Options** button to calculate S Factors. The **Standardize** window appears:

As the window loads, a net-intensity calculation is performed on the current spectrum using the current element list, background methods and background points.

🔚 Standardize	
S Factors	── Organic Matrix Epxy Res
Concentrations           SiK         1.00           ClK         1.00	Name : Epxy Res Z^2/A : 3.06
K K 1.00 CaK 1.00	Change Calculate
Calculate	
Water Factor Z <sup>*</sup> 2/A H2O : 0.1179	OK Cancel

- 1. Highlight each element in the scrolling list in turn and enter its concentration in the **Concentrations** field.
- 2. Click on the **Calculate** button and the current net intensities will be used to calculate experimental S factors. The results of the calculation will appear in the **Calculated S Factors** window.

Any or all of these values can be used to update the current user table. To do so:

- 1. Highlight the elements whose S Factors you want to update.
- 2. Click on the Update S Factors check box.

Calculate	ed S Factors		
Ele	em Calc'	d Current	
SiK	58.5	2 60.00	
ClK	21.1	.0 44.99	
K K	18.8	42.37	
CaK	127.4	7 40.60	
	🗆 Update S	Factors	
		1 actors	
	0	ĸ	

3. Click on **OK** when finished updating.

## 10.1.5 Organic Matrix

#### Selecting Organic Matrix

The Organic Matrix to be used in calculations may be selected in the Standardize Dialog Box. To choose the organic matrix:

- 1. Click on the combobox.
- 2. Choose from the following choices
  - Epoxy Resin
  - Gelatin
  - Albumin
  - FD Liver
  - FD Heart
  - FH Liver
  - FH Heart

The name and Z-squared over A value is displayed. (where Z is the atomic number and A is the atomic weight)

#### User Values for Organic Matrix

It is possible to calculate the organic matrix and save up to three values as user values. To calculate the value

- 1. Select User 1, User 2 or User 3 in the combobox
- 2. Enter a value manually and click the Change button or
- 3. Click on the **Calculate** button. The Organic Matrix dialog box appears. Values for elements can be entered by Number of Atoms or by Weight %.

0	rganic Matrix	×
0	Number of Atoms	C Weight %
	Element :	Add
	Num Atoms:	Delete
	Element	Num Atoms
	Calculate	Z^2/A :
	ОК	Cancel

To Calculate the Value by Number of Atoms

- 1. Choose the Number of Atoms radio button.
- 2. Enter element symbol and number of atoms for each element
- 3. Click Add to the add the element and value to the list.
- 4. Click Calculate. The Z-Squared over A value is displayed.
- 5. To accept the value, click the **OK** button.

To Calculate the Value by Weight Percent

- 1. Choose the **Weight %** radio button.
- 2. Enter element symbol and weight percent value for each element
- 3. Click **Add** to the add the element and value to the list.

- 4. Click Calculate. The Z-Squared over A value is displayed.
- 5. To accept the value, click the **OK** button.

#### Saving User Z-Squared/A Values

Once the value has been calculated, enter a name for the value. The User value calculated is saved when the **OK** button on the **Standardize** dialog box is clicked. These values are saved for all subsequent calculations.

## **10.1.6 Starting Quantification**

There are three stages of operation for biological quantification. Grid, Film and Sample quantifications must be done in a specific order. Grid and Film results are used in all subsequent Sample quantifications.

1. Grid - Acquire a spectrum from a grid of the type being used for all standards and samples.

- Set the Sample type to Grid
- This automatically sets the results type to Grid
- Set the background and S Factors as described earlier.
- Acquire the spectrum for the grid sample
- Click the Quantify button
- The results will display:

Quantification Results	×
D:\EDAX32\BTHIN\USR\Dxgrid.spc	
Biological Results , User S Factors Continuous Peak	
Grid : Dxgrid.spc 50.31 485.28	
Element Net Inte. Backgrd Inte. Error P/B	
NiK 415.49 2.03 0.49 204.67	
र	<u> </u>
Page Setup Print Results Print Spc and Results	Ok

- 2. Film Acquire a spectrum from the supporting film.
  - Set the Sample type to Film
  - This automatically sets the results type to Film
  - Set the background and S Factors as described earlier.
  - Acquire the spectrum for the film sample
  - Click the Quantify button
  - The results will display:

🔲 Quantificatio	n Results				×
D:\EDAX32	2\BTHIN\USR	\Dxfilma.	spc		<b>_</b>
Biologica	al Results		Factors inuous Pe	eak	
Grid : Film :	Dxgrid.s Dxfilma.s	рс 50 рс 22	.31 485 .53 36	.28 .89	
Element	Net Inte.	Backgrd	Inte. Error	Р/В	
SiK Clk	0.39		3.58 55.05		
кк	0.57	1.56	33.70	0.37	•
Page Setur	Print R		Print Spc and Re		
Fage Setup		esuits	Finit opt and Re	sours	OK

- 3. Unknown or Standard sample
  - Set the Sample type to Sample
  - This automatically sets the results type to Sample
  - Set other fields in the status panel for the background and S Factors
  - Set the Hydrate/Dry or Peripheral Std. radio buttons
  - Set the **Unknown** or **Standard** by right mouse clicking to the right of the Quant button.
  - Acquire the spectrum for the sample
  - Click the Quantify button

• The results will display:

Quantification D:\EDAX32\	Results BTHIN\USR\Dxst	da01.spc		
Biological Sample - U	Results , Use	r S Factors		
		Inte. Ratio		
 SiK	18.69	0.52		
CIK	51.84	1.44		
кк	58.12	1.62		
CaK	8.58	0.24		
IC / B1	57.66			
		Continuous	Peak	_
4				
Page Setup	Print Results	Print Spc and	Results	Ok

The above table gives the net intensities from the sample. In order to get concentrations, the Results type of CONC needs to be selected. Click on results in the expanded Quant panel. Check the Conc box.



Then clicking on the Quant button will give the final results:

All the data specified for display in the page-setup options are listed and accessed by scrolling.

Element	Inten SFa	actor Wgt %	. mMole/Kg	-
SiK	0.52 60.	.00 1.06	376.65	
CIK	1.44 44.	.99 2.20	620.58	
КК	1.62 42.	.37 2.32	594.10	
CaK	0.24 40.	.60 0.33	81.99	
Number of	· Iterations :	: 3		
		Continuous	Peak	
Grid :	Dxgrid.spc	50.31	485.28	
Film :		22.53		_
Sample :	Dxstda01.spc		73.78	
	-			
1				

You can now change the format in which results are displayed by pressing the **Page Setup** button and specifying the new format.

🔚 Page Setup			×		
<ul> <li>✓ Filename</li> <li>✓ Label</li> <li>✓ Parameters</li> </ul>		I Date and	strum		
Spectrum					
<ul> <li>✓ Count Status</li> <li>✓ Outline Mode</li> <li>✓ Border</li> <li>✓ Overlay</li> <li>✓ Axis/Grid</li> <li>✓ Deconvolution</li> <li>✓ Element Markers</li> <li>✓ Background</li> <li>✓ Color</li> <li>✓ Black and White</li> </ul>					
Margins       Top : 1.00       in       Left : 1.00       In					
	Ok	Cancel			

## 10.1.7 Printing

To print the results of the quantification calculation click on either the Print Results button or the **Print Spc and Results** button in the **Quantification Results** window.

## 10.1.8 Results Options

After you have obtained your quantification results, you have two options:

- Save
- Show

#### Save

The Save option allows you to save the quantification results to disk. To do so:

1. Click on the **Save** button.

Save As					? ×
Save jn:	🔁 Usı	•	£	Ċ	0-0- 0-0- 0-0-
I					
File <u>n</u> ame:	Dxstda01.csv				<u>S</u> ave
Save as <u>type</u> :	Comma Sep Val (*.csv)		•		Cancel

The standard Windows save options appear.

You can save results in two file formats:

- Comma-separated values (.CSV files)
- Binary format (.DAT files).

CSV files are in ASCII format and compatible with spread-sheets and word processors.

DAT files are a compact binary format, compatible with EDAX software.

Show

The Show option is used to redisplay the Quantification Results window.